



Garden Grove Fire Department
 Station: G05
 Shifts Or Platoon: B

Location: 8242 CENTRAL AVE Garden Grove CA 92640	Incident Type: 131 - Passenger vehicle fire
Lat/Long: N 33° 46' 12.01" W 117° 59' 7.78"	FDID: 30035 Incident #: 2017-711785 Exposure ID: 27704720 Exposure #: 0 Incident Date: 10/16/2017 Dispatch Run #: F172890417
Location Type: 1 - Street address Map Page: 798A7	

Report Completed by:	Nguyen , Thanh	ID: 167	Date: 10/18/2017
Report Reviewed by:	Nguyen , Thanh	ID: 167	Date: 10/18/2017
Report Printed by:	Nguyen, Thanh	ID: 167	Date: 10/23/2017 Time: 10:20

Structure Type:	Property Use: 419 - 1 or 2 family dwelling		
Automatic Extinguishment System Present: <input type="checkbox"/>	Detectors Present: <input type="checkbox"/>	Cause of Ignition: Cause undetermined after investigation	
Aid Given or Received: None	Primary action taken: 11 - Extinguishment by fire service personnel		
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 1		Total # of personnel on call: 4	

Narrative from dispatch:

<p>NARRATIVE (2)</p> <p>Narrative Title: Fire - Vehicle</p> <p>Narrative Author: Nguyen, Thanh</p> <p>Narrative Date: 10/18/2017 07:47:53</p> <p>Narrative Apparatus ID: GE5</p> <p>Narrative:</p> <p>GE5 arrived on scene to find a car in a driveway of a private residence. A resident was attempting to extinguish with a garden hose. GE5 forced entry into the engine compartment with a powered saw, and extinguished the fire. The owner stated that his car had a sensor problem, and had not had any work done on it recently. The cause of the fire is undetermined.</p> <p>Capt. Nguyen</p>

APPARATUS	
Unit	GE5
Type:	Engine
Use:	Suppression
Response Mode:	()
# of People	4
Alarm	10 /16/2017 23:25:49
Dispatched	10 /16/2017 23:26:00
Enroute	10 /16/2017 23:27:22
Arrived	10 /16/2017 23:33:24
Cancelled	-- / -- / -- -- : -- : --
Cleared Scene	10 /16/2017 23:59:00
In Quarters	-- / -- / -- -- : -- : --
In Service	-- / -- / -- -- : -- : --
Number Of People not on apparatus: 0	

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Engine area, running gear, wheel area	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause undetermined after investigation
Factor Contributing To Ignition	Mechanical failure, malfunction, other		
Human Factors Contributing	None		
Mobile Property Involve And Type	Not involved in ignition, but burned	Mobile Property Type	Automobile, passenger car, ambulance, race car
Mobile Property Make	Mazda	Mobile Property Year	2004
Mobile Property Model	Tribute	License Plate	4TY890
State	CA	VIN	

ARSON		
Agency Name	Agency Address	Agency Phone

PEOPLE -- PERSON 1			
Telephone Number	6573406632	Involvement	Caller
Name	T-MOBILE (877) 653-7911	Date of Birth	
Address	8062 GARDEN GROVE BLVD CA 00000-		

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service

Member Making Report (Captain Thanh Nguyen): _____

Supervisor (Captain Thanh Nguyen): _____