

Garden Grove Fire Department

Station: G05 Shifts Or Platoon: B

Location:
12738 JOSEPHINE ST
Garden Grove CA 92640

Lat/Long: N 33° 46′ 39.37" W 117° 58′ 45.6″

Location Type: 1 - Street address Map Page: **798B6**

Exposure #: 0 Incident Date: 10/20/2017 Dispatch Run #: **F172930054**

Incident #: 2017-711922

Exposure ID: **27785473**

Incident Type: 111 - Building fire

FDID: 30035

Report Completed by:	Nguyen , Thanh	ID: 167	Date: 10/24/2017	
Report Reviewed by:	Nguyen , Thanh	ID: 167	Date: 10/24/2017	
Report Printed by:	Guardi, Lisa	ID: 4433	Date: 11/16/2017 Time: 14:21	

Structure Typ	e: Enclosed building	Property	Use: 429 - Multifam	ily dwell	ling	
Automatic Ex	tinguishment System Pre	sent:	Detectors Present:	Cause of	Ignition: Cause undetermined investigation	after
Aid Given or I	Aid Given or Received: Automatic aid received Primary action taken: 11 - Extinguishment by fire service personnel					
Additional act	Additional actions: 21 - Search , 86 - Investigate					
Losses	Pre-Incident Value	es				
Property:	Property:		Civilian Injuries:	0	Fire Service Injuries:	0
Contents:	Contents:		Civilian Fatalities:	0	Fire Service Fatalities:	0
Total:	Total:		Total Casualties:	0	Total Fire Service Casualties:	0
Total # of ap	paratus on call:		9 Total #	of person	nel on call:	17

Total # of apparatus on call:	9	Total # of personnel on call:	17
Narrative from dispatch:			
[10/20/17 11:56:10 M072] GE5 BLDG DEPARTMENT OS	. ou	T OF SERVICE FOR 30 MIN	
[10/20/17 11:15:23 M079] DUPE CALLS 54 61	,		
[10/20/17 11:07:30 M079] DUPE CALLS 54 56 57 58			
[10/20/17 09:53:46 M072] GB1 GE7 RELEASED, GE5/GB	E1/G	T1 REMAIN OS, GE5 POINT OF CONTACT, 2N CLEAR	
[10/20/17 09:22:33 M072] GB1 GM1/GE6 RELEASED			
[10/20/17 09:14:14 M072] GE2 COMMUNICATION LINE	S TC	THE REAR OF CHARLIE DIVISION NON FUNCTIONAL	
[10/20/17 08:56:26 M035] RED CROSS UPDATED, 8 AD	ULTS	5/3 CHILDREN	
[10/20/17 08:53:33 M072] GB1 8 ADULTS/3 CHILDREN	DIS	PLACED	
[10/20/17 08:53:06 M072] GE6 2 ADULTS 3 CHILDREN			
[10/20/17 08:51:28 M072] GE6 2 ADULTS DISPLACED F			
[10/20/17 08:45:20 M072] GB1 REQ REDCROSS, 4 ADU	ILTS	DISPLACED	
[10/20/17 08:31:34 M072] GB1 CB1/AT6 RELEASED			
[10/20/17 08:27:52 M072] GB1 REQ EDISON			
[10/20/17 08:26:17 M072] INCIDENT CLOCK STOPPED:			
[10/20/17 08:26:14 M072] GB1 STOP THE INCIDENT C	LOCK	(
[10/20/17 08:26:01 M072] GE6 EXPOSURE			
[10/20/17 08:25:54 M072] GB1 CANCELLED GE3			
[10/20/17 08:25:37 M072] INCIDENT CLOCK ACKED: 08			
[10/20/17 08:25:24 M072] GB1 ADV IC 30 MIN ON INC			
[10/20/17 08:24:58 M079] GDIV1ADV, L/M ON CELL PH			
[10/20/17 08:24:49 M072] GB1 GE6 ASSIGNED TO EXP	OSUI	RE .	
[10/20/17 08:24:29 M072] GB1 CANCELLED AUSAR2			
[10/20/17 08:24:06 M072] AUSAR2 OS GILBERT/KATEL			
[10/20/17 08:23:20 M072] AT6 GAS/ELECTRICAL ARE C		20,02	
[10/20/17 08:23:03 KOPS] INCIDENT CLOCK ELAPSED: [10/20/17 08:22:44 M072] GE1 DELTA SIDE CLEAR, NO			
[10/20/17 08:22:29 M072] GB1 FIRE KNOCKDOWN AT			
[10/20/17 08:22:25 M072] GBT FIRE KNOCKDOWN AT			
[10/20/17 08:22:13 M072] GE1 EXPOSURE	,	MIFEL IE KNOCKDOWN	
[10/20/17 08:21:33 M072] GE1 EXPOSORE [10/20/17 08:21:22 M072] GE2 CHARLIE/DELTA SIDE C	OVE	RED. DELTA LOOKS CLEAR	
[10/20/17 08:20:22 M079] PER GGPD, THEY ARE OS FO			
[10/20/17 08:20:09 M072] GE3 OS W/3	ZIX 11	VIII TO CONTINUE	
[10/20/17 08:19:58 M072] GE1 ALPHA/BRAVO CLEAR, (CHEC	K DELTA SIDE	
	_,	······································	

```
[10/20/17 08:19:13 M080] GB1 PAGED MOVE UPS COMPLETE
[10/20/17 08:18:59 M072] CB1 SAFTEY
[10/20/17 08:18:55 M072] GB1 CB1 ASSUMED SAFTEY
[10/20/17 08:17:12 M072] GE6 OS W/3
[10/20/17 08:17:02 M072] GE5 KNOCKDOWN, COMING OUT FOR AIR, GE7 CHECKING FOR EXTENSION
[10/20/17 08:15:41 M072] GE5 COMPLETED PRIMARY, WE HAVE KNOCKDOWN
[10/20/17 08:15:00 M072] GM1 FIRE ATTACK
[10/20/17 08:14:54 M072] GB1 GM1 ASSIGNED TO FIRE ATTACK, ASSIST W/SECONDARY CLEAR
[10/20/17 08:14:33 M072] GM1 OS W/2
[10/20/17 08:13:57 M072] INCIDENT CLOCK ACKED: 08:13:57
[10/20/17 08:13:07 M072] GE1 ON ALPHA SIDE NO EXTENSION, CANNOT MAKE IT TO CHARLIE/DELTA SIDE FOR CHECK
[10/20/17 08:11:17 M072] GB1 UPGRADE 2ND ALARM
[10/20/17 08:11:07 M080] Updated to ALARM LEVEL 2.
[10/20/17 08:10:55 M072] GE5 PRIMARY CLEAR, REQ ADDL MAN POWER FOR SECONDARY
[10/20/17 08:09:39 M072] AT6 VENT
[10/20/17 08:09:33 M072] GB1 AT6 ASSIGNED VENT GROUP
[10/20/17 08:08:51 M072] AT6 OS W/4 STAGED JOSEPHINE/LAMPSON
[10/20/17 08:08:27 M072] GT1 HEADING TO 3RD UNIT FOR VENTILATION
[10/20/17 08:08:10 M072] GE2 POSSIBLE EXTENSION TO ATTIC
[10/20/17 08:08:03 KOPS] INCIDENT CLOCK ELAPSED: 08:08:03
[10/20/17 08:07:48 M072] GE2 SMOKE FROM MULTIPLE VENTS ON ROOF
[10/20/17 08:07:32 M072] GB1 GE1 ASSIST EXPOSURE GROUP, CHECK FOR EXTENSION
[10/20/17 08:07:12 M072] GE1 OS W/3 FROM SOUTH
[10/20/17 08:06:00 M072] GE2 CHARLIE DIVISION
[10/20/17 08:05:49 M072] GE2 SC Removed
[10/20/17 08:05:41 M072] GB1 GE2 IS NOW DIVISION CHARLIE
[10/20/17 08:04:45 M072] GB1 JOSEPHINE COMMAND
[10/20/17 08:04:37 M072] GE7 FIRE ATTACK
[10/20/17 08:04:32 M072] GT1 VENT
[10/20/17 08:04:28 M072] GE2 EXPOSURE
[10/20/17 08:04:23 M072] GB1 GE7 ASSIST W/FIRE ATTACK
[10/20/17~08:04:04~M072]~	ext{GB1}~OS, ASSUMING JOSEPHINE COMMAND, COMMAND POST AT JOSEPHINE NORTH OF
INCIDENT, GE5 FIRE ATTACK, GT1 VENT, GE2 EXPOSURE, ALPHA SIDE TACTICAL
[10/20/17 08:03:13 M072] GE5 BEST ACCESS FROM JOSEPHINE
[10/20/17 08:02:20 M072] GT1 OS W/3
[10/20/17 08:01:38 M072] GE2 HITTING FIRE FROM EAST SIDE, FLAMES ON WIRES
[10/20/17 08:00:19 M072] GE5 FIRE ATTACK
[10/20/17 08:00:10 M072] GE5 OS JOSEPHINE, 12724 JOSEPHINE, SINGLE STORY DUPLEX/MULTIPLEX, HEAVY SMOKE,
FIRE ATTACK
[10/20/17 08:00:04 M080] CB1 AVAIL INC 54
[10/20/17 07:58:58 M072] GB1 UPGRADE TO WORKING
[10/20/17 07:58:54 M080] Situation Updated: 167 (STRUCTURE FIRE-WORKING)
[10/20/17 07:58:00 M072] GE2 ONE STREET TO WEST OF REPORTED ADDR, BACKYARD OF RES AT THAT LOCATION
[10/20/17 07:56:35 M072] GE2 SMOKE TO REAR OF RES, DETERMINING IF RES OR RES ON STREET TO WEST, INV,
CONTINUE C3
[10/20/17 07:56:08 M027] INC DUPE TO 54/61
[10/20/17 07:55:29 M079] DUPE CALLS 57 54
[10/20/17 07:55:09 M072] DUPE CALLS 54 56
[10/20/17 07:53:03 M080] INCIDENT CLOCK STARTED: 07:53:03 FOR 15 MINUTES
```

[10/20/17 07:53:03 M080] Situation Updated: 166 (STRUCTURE FIRE-RESIDENTIAL)

NARRATIVE (2)

Narrative Title: Structure Fire Narrative Author: Nguyen, Thanh Narrative Date: 10/24/2017 11:39:33

Narrative Apparatus ID: GE5

Narrative:

GE2 responded to the originally given address on Aristocrat for a pole fire. While en route, the incident was upgraded to a structure fire. GE2 responded to the address, and reported smoke coming from one street over. GE5 responded to Josephine Street which was one street west of the original address.

GE5 arrived on scene, and reported smoke showing from a single story multiplex structure. GE5 updated an address of 12724 Josephine Street which was visible from the street. GE5 initiated fire attack with an apartment lay, and requested support with a second handline. GE5 found a resident attempting to extinguish with a garden hose, and ordered the resident and others to stay away. GE5 and GE7 affected fire attack, and GT1 performed vertical ventilation. GB1 upgraded the incident to a working structure fire, and later to a second alarm. Additional crews shut off utilities to the building, and Edison dropped the line to the structure. It took fire fighters approximately 30 minutes to get the fire under control. A search of the apartment did not find any people.

The fire was investigated by Captain Weiss. The cause of the fire was undetermined after investigation.

There was no reported injuries to fire fighters or residents except for one male resident who requested a bandaid for his toe. He did not ask for EMS assistance. The City building department was requested, and an inspector red-tagged the building due to power and all other utilities being shut off. A total of 11 residents out of three units were displaced, and the Red Cross was on scene to provide assistance.

The tenant of the unit involved in fire, Van Vo, signed the fire department Property Release form and instructed to follow instructions on the form and to contact her insurance company. A copy of the form was given to her, and she was advised on how to obtain a fire report.

Capt, Nguyen

re Controlled Date	/ Time:	10/20/2017 11:56:24 AM	282 E W =
nit	GB1	Unit	GE1
ype:	Chief officer car	Type:	Engine
se:	Suppression	Use:	Suppression
esponse Mode:	Q	Response Mode:	()
of People	1	# of People	1
larm	10 /20/2017 07:48:15	Alarm	10 /20/2017 07:48:15
ispatched	10 /20/2017 07:50:04	Dispatched	10 /20/2017 07:50:04
nroute	10 /20/2017 07:54:58	Enroute	10 /20/2017 08:00:14
rrived	10 /20/2017 08:04:54	Arrived	10 /20/2017 08:13:19
ancelled	'/ / : :	Cancelled	/ / : :
leared Scene	10 /20/2017 10:32:08	Cleared Scene	10 /20/2017 10:54:54
n Quarters	10 /20/2017 10:32:08	In Quarters	10 /20/2017 10:54:54
Service	10 /20/2017 10:32:08	In Service	10 /20/2017 10:54:54
nit	GE2	Unit	GE3
ype:	Engine	Туре:	Engine
se:	Suppression	Use:	Suppression
esponse Mode:		Response Mode:	
of People	1	# of People	0
larm	10 /20/2017 07:48:15	Alarm	10 /20/2017 07:48:15
ispatched	10 /20/2017 07:50:04	Dispatched	10 /20/2017 07:50:04
nroute	10 /20/2017 07:51:19	Enroute	10 /20/2017 08:11:35
rrived	10 /20/2017 07:56:37	Arrived	10 /20/2017 08:20:11
ancelled	/ / : :	Cancelled	10 /20/2017 08:30:00
leared Scene	10 /20/2017 10:20:31	Cleared Scene	10 /20/2017 08:40:09
1 Quarters	10 /20/2017 10:20:31	In Quarters	10 /20/2017 08:40:09
n Service	10 /20/2017 10:20:31	In Service	10 /20/2017 08:40:09
nit	GE5	Unit	GE6
/pe:	Engine	Туре:	Engine
se:	Suppression	Use:	Suppression
esponse Mode:		Response Mode:	
of People	4	# of People	1
larm	10 /20/2017 07:48:15	Alarm	10 /20/2017 07:48:15
spatched	10 /20/2017 07:50:04	Dispatched	10 /20/2017 07:50:04
route	10 /20/2017 07:53:28	Enroute	10 /20/2017 07:52:00
rrived	10 /20/2017 08:01:52	Arrived	10 /20/2017 08:17:14
ancelled	/ / :	Cancelled	/ / : :
eared Scene	10 /20/2017 11:56:24	Cleared Scene	10 /20/2017 09:52:11
Quarters	/ / : :	In Quarters	10 /20/2017 09:52:11
Service	10 /20/2017 11:56:24	In Service	10 /20/2017 09:52:11
nit	GE7	Unit	GM1
/pe:	Engine	Type:	ALS unit
se:	Suppression	Use:	Suppression
esponse Mode:	0	Response Mode:	. ()
of People	3	# of People	2
arm	10 /20/2017 07:48:15	Alarm	10 /20/2017 07:48:15
ispatched	10 /20/2017 07:50:04	Dispatched	10 /20/2017 07:50:04
route	10 /20/2017 07:54:36	Enroute	10 /20/2017 08:03:43
rived	10 /20/2017 08:06:16	Arrived	10 /20/2017 08:14:35
ncelled	/ / : :	Cancelled	-/-/:
eared Scene	10 /20/2017 10:31:14	Cleared Scene	10 /20/2017 09:46:20
Quarters	10 /20/2017 10:31:14	In Quarters	10 /20/2017 09:46:20
Service	10 /20/2017 10:31:14	In Service	10 /20/2017 09:46:20
it	GT1		o p. sa materialesia Lagrandia I, e metallituda "attenda attenda este esta este esta este esta esta est
pe:	Truck or aerial	· NAME CONTROL OF	
<u> </u>	Suppression	of the finance of the first of	
esponse Mode:	()	and anytheraction and	
of People	3	AND sparkman marketopes	
arm	10 /20/2017 07:48:15	And Andread Andread	
spatched	10 /20/2017 07:50:04	se allegation	•
route	10 /20/2017 07:54:20	· · · · · · · · · · · · · · · · · · ·	
rived	10 /20/2017 07:54:20	delenating- one	
ancelled	/ / : ;	dender Address	
eared Scene	10 /20/2017 11:42:22	makkin asunindanah	
Quarters		annument of the second of the	
Service	10 /20/2017 11:42:22		
SCI VILE	10 /20/2017 11:42:22		

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Outside area, other	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	Additional values described in the control of the state o
Type Of Material	Undetermined	Cause Of Ignition	Cause undetermined after investigation
Factor Contributing To Ignition	Undetermined	and the same and development and all assess and assess properties are some vertical and "with all assess are properties and assess and asset asset as a second as a second asset as a second asset as a second asset as a second as a second as a second as a second a	
Human Factors Contributing	None		от при при поторожно в поторожно форман и то при при при поторожно по при

	· · ·	
Enclosed building	Building Status	In normal use
1	# Of Stories Below Grade	0
800	Length	
	Floor Of Origin	1
Confined to building of origin		
0	Significant Damage	0
O	Extreme Damage	0
Undetermined	Type Of Material Contributing Most To Spread	orvare Ishali-arases Tragasini andrifatasan area Esharan area idasan area (dassanan ara
Present	Type Of Detection System	Undetermined
Battery only	Detector Operation	Detector operated
Detector failed to alert occupants	Detector Failure Reason	And Andrews and An
	1 800 Confined to building of origin 0 0 Undetermined Present Battery only Detector failed to alert	1 # Of Stories Below Grade 800 Length Floor Of Origin Confined to building of origin 0 Significant Damage 0 Extreme Damage Undetermined Type Of Material Contributing Most To Spread Present Type Of Detection System Battery only Detector failed to alert Detector Failure Reason

ARSON		
Agency Name	Agency Address	Agency Phone

PEOPLE PERSON 1			
Telephone Number	5623222953	Involvement	Caller
Name	T-MOBILE (877) 653-7911	Date of Birth	- Trainingspungspungspungspungspungspungspungspu
Address	9042 GARDEN GROVE BLVD CA 00000-	indes artiklyringelvert tripolesaringischtskirliseskiskirdakirdakki skirindommuseriaarinmiskus siita. 4. aapaamuse	hi M. s-rumpun _n a mere iling das glide terus-disabilite meterbanete eritina usan a merijk ordam d

CUSTOM FIELDS FORM		
What happened?	We provided fire and rescue service	

Member Making Report (Captain Thanh Nguyen):	
	"
Supervisor (Captain Thanh Nguyen):	