

Garden Grove Fire Department

Station: **G06**Shifts Or Platoon: **A**

Location: 10861 SIDNEY PL Garden Grove CA 92640

Lat/Long:

N 33° 47′ 23.56″ W 117° 56′ 36.95″

Location Type: 1 - Street address
Map Page: 798F4

Incident Type:

111 - Building fire

Incident #: 2017-714825 Exposure ID: 29025043

Exposure #: 0

FDID: 30035

Incident Date: **12/25/2017**Dispatch Run #: **F173590356**

Report Completed by:	Acosta , Tony R	ID: 12	Date: 12/27/2017
Report Reviewed by:	Not Reviewed		
Report Printed by:	Guardi, Lisa	ID: 4433	Date: 1/11/2018 Time: 11:17

Structure 7	ype: Enclosed b	uilding Pro	operty Use:	419 - 1	or 2 far	nily dwelli	ing		
Automatic	Extinguishment Sy	stem Preser	nt: Dete	ctors Pre	sent:	Cause of I	gnitio	n: Unintentional	
Aid Given	or Received: Auto	omatic aid	received	Primary	action ta	ken: 10 -	Fire	control or extinguishment,	other
Losses		Pre-Incid	ent Values	3	Ė	*			,
Property:	\$30,000.00	Property:	\$650,000	0.00	Civilian	Injuries:	0	Fire Service Injuries:	0
Contents:	\$20,000.00	Contents:	\$60,000.	.00	Civilian	Fatalities:	0	Fire Service Fatalities:	0
Total:	\$50,000.00	Total:	\$710,000	0.00	Total Ca	sualties:	0	Total Fire Service Casualties:	0
Total # of	apparatus on call:			6	Total #	of personn	el on	call:	16

```
Narrative from dispatch:
[12/25/17 22:42:36 M058] GE6 SCENE CONTACT
[12/25/17 22:35:05 M081] GB1 RELEASE GM1, AOR. SCENE LEFT WITH GE6/GT1
[12/25/17 21:54:35 M048] RED CROSS HAS BEEN REQ, WCB WITH AN ETA
[12/25/17 21:51:27 M081] GB1 GM1 WILL BE AVAIL OS
[12/25/17 21:50:03 M048] GB1 REQ RED CROSS, 7 PEOPLE DISPLACED
[12/25/17 21:40:57 M048] INCIDENT CLOCK STOPPED: 21:40:57
[12/25/17 21:40:29 M048] GB1 CANCELLED AE6
[12/25/17 21:39:47 M048] INCIDENT CLOCK ACKED: 21:39:47
[12/25/17 21:39:41 KOPS] INCIDENT CLOCK ELAPSED: 21:39:41
[12/25/17 21:38:03 M048] AT6 UTILITIES HAVE BEEN SECURED
[12/25/17 21:35:10 M048] GM1 ASSIST VENT GROUP
[12/25/17 21:31:55 M048] GM1 OS WITH 2
[12/25/17 21:28:35 M048] GB1 REQ AT6 TO SECURE UTILITIES
[12/25/17 21:28:01 M048] AT6 SALVAGE GROUP
[12/25/17 21:27:47 M048] AT6 SALVAGE
[12/25/17 21:27:41 M048] AT6 OS WITH 4
[12/25/17 21:27:33 M048] AE6 OS
[12/25/17 21:26:59 M048] AB2 SAFETY
[12/25/17 21:26:36 M048] GE6 VENT GROUP WILL EXTEND THE HOLE
[12/25/17 21:25:28 M048] GE6 SMALL FIRE INSIDE THE CEILING
[12/25/17 21:24:51 M048] INCIDENT CLOCK ACKED: 21:24:51
[12/25/17 21:24:46 M048] GE1 INTERIOR
[12/25/17 21:24:41 KOPS] INCIDENT CLOCK ELAPSED: 21:24:41
[12/25/17 21:23:55 M048] GM1 GLF1
[12/25/17 21:23:55 M048] GE1 GLF1
[12/25/17 21:22:18 M048] GE1 FIRE ATTACK
[12/25/17 21:22:04 M048] GE6 PRIMARY ALL CLEAR, LIGHT HAZY CONDITIONS IN THE HOME
[12/25/17 21:21:21 M081] Situation Updated: 167 (STRUCTURE FIRE-WORKING)
```

[12/25/17 21:21:01 M048] GB1 REQ WF

[12/25/17 21:20:48 M048] GT1 EXTENSION IN THE ATTIC, REQ ADDL LINE TO THE ROOF

[12/25/17 21:20:25 M048] GB1 GE1 TO CHECK THE INTERIOR

[12/25/17 21:18:34 M048] GT1 VENT GROUP

[12/25/17 21:17:10 M048] GB1 SIDNEY COMMAND

[12/25/17 21:16:56 M048] GE6 FIRE ATTACK

[12/25/17 21:16:33 M048] GE6 CHIMNEY FIRE, IN THE CHUTE, REQ TRUCK TO LADDER

[12/25/17 21:16:09 M048] GE2 OS WITH 4

[12/25/17 21:15:09 M048] GE1 OS WITH 3

[12/25/17 21:14:42 M048] GE6 OS WITH 3, SINGLE STORY HOUSE, LIGHT SMOKE FROM THE BACK YARD, RESIDENCE

OUTSIDE, INV

[12/25/17 21:09:42 M058] INCIDENT CLOCK STARTED: 21:09:42 FOR 15 MINUTES

NARRATIVE (2)

Narrative Title: Fire

Narrative Author: Garcia, Drew

Narrative Date: 12/27/2017 14:57:11

Narrative Apparatus ID: GE1

Narrative:

Residential Structure Fire

GE1 responded to the reported address and completed GE6 water supply. GE1 was assigned Interior and subsequently had AT6, GM1, and GE2 assigned to assist with salvage in the interior. Interior crews moved all valuables out of the way to protect from water damage. Visqueen was used to cover all valuables and electronics. GE1 complete.

Captain Garcia

NARRATIVE (3)

Narrative Title: FIRE RESIDENTIAL
Narrative Author: Breneman, Jerry
Narrative Date: 12/27/2017 18:44:53

Narrative Apparatus ID: GE2

Narrative:

GE2 ARRIVED AS 3RD IN ENGINE OF A RESIDENTIAL STRUCTURE FIRE. GE2 WAS ASSIGNED TO ASSIST VENT GROUP WITH AN ADDITIONAL LINE ALOFT. VENT GROUP WITH ADEQUATE MANPOWER. IC ADVISED. GE2 WAS REASSIGNED TO ASSIST INTERIOR WITH SALVAGE. INTERIOR ALSO WITH ADEQUATE RESOURCES. IC ADVISED. GE2 WAS RELEASED FROM THE SCENE. GE2 COMPLETED.

NARRATIVE (4)

Narrative Title: Chimney Fire
Narrative Author: Acosta, Tony
Narrative Date: 12/27/2017 18:52:29

Narrative Apparatus ID: GE6

Narrative:

GE6 RESPONDED TO A SINGLE STORY HOUSE WITH REPORTS OF A POSSIBLE CHIMNEY FIRE. UPON ARRIVAL, LIGHT TO MODERATE SMOKE WAS SEEN FROM THE TOP OF THE CHIMNEY AND TO THE REAR OF THE RESIDENCE. GE6 INVESTIGATED AND SAW SMOKE AND SMALL FLAMES SEEN AT THE TOP OF THE CHIMNEY. GE6 INITIATED FIRE ATTACK WITH A PRE-CONNECT AND UTILIZED GT1 FOR VERTICAL VENTILAITON AND TO CHECK TO SEE IF WE HAD EXTENSION TO THE VOID SPACE IN THE ROOF RAFTERS. AFTER GT1 OPENED UP THE ROOF, SOME FIRE WAS SEEN IN THE VOID SPACE AND IN THE SPACE SURROUNDING THE CHIMNEY FLUE. THE STUCCO AROUND THE CHIMNEY WAS OPENED UP USING A ROTARY SAW AND FIRE WAS VISIBLE IN THE VOID SPACE. FIRE ATTACK WAS INTITIATED ON THE ROOF TO CONTAIN THE AND EXTINGUISH THE FIRE IN THE VOID SPACE SURROUNDING THE CHIMNEY FLUE. AFTER EXTINGUISHMENT WAS OBTAINED, THE ENTIRE WAS AREA WAS COOLED DOWN WITH WATER AND FOAM. CAPTAIN ACOSTA CONSULTED WITH THE HOMEOWNER AND RELEASE OF LIABILITY FORM WAS SIGNED. HOMEOWNER WAS INSTRUCTED TO NOT INHABIT THE HOUSE UNTIL BUILDING DEPT DEEMED IT SAFE TO RE-ENTER.

CAPTAIN T ACOSTA

PPARATUS			*
Unit	GB1	Unit	GE1
Туре:	Chief officer car	Туре:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	()	Response Mode:	0
# of People	1	# of People	3
Alarm	12 /25/2017 21:08:16	Alarm	12 /25/2017 21:08:16
Dispatched	12 /25/2017 21:09:42	Dispatched	12 /25/2017 21:09:42
Enroute	12 /25/2017 21:11:16	Enroute	12 /25/2017 21:10:13
Arrived	12 /25/2017 21:15:33	Arrived	12 /25/2017 21:15:16
Cancelled	/ / : :	Cancelled	/ / ::
Cleared Scene	12 /25/2017 23:16:21	Cleared Scene	12 /25/2017 23:10:08
In Quarters	12 /25/2017 23:16:21	In Quarters	12 /25/2017 23:10:08
In Service	12 /25/2017 23:16:21	In Service	12 /25/2017 23:10:08
Unit	GE2	Unit	GE6
Type:	Engine	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	_ ()
# of People	4	# of People	3
Alarm	12 /25/2017 21:08:16	Alarm	12 /25/2017 21:08:16
Dispatched	12 /25/2017 21:09:42	Dispatched	12 /25/2017 21:09:42
Enroute	12 /25/2017 21:12:10	Enroute	12 /25/2017 21:10:49
Arrived	12 /25/2017 21:16:11	Arrived	12 /25/2017 21:14:45
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	12 /25/2017 22:06:12	Cleared Scene	12 /25/2017 23:19:38
In Quarters	12 /25/2017 22:06:12	In Quarters	12 /25/2017 23:19:38
In Service	12 /25/2017 22:06:12	In Service	12 /25/2017 23:19:38
Unit	GM1	Unit	GT1
Type:	ALS unit	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	()	Response Mode:	O
# of People	2	# of People	3
Alarm	12 /25/2017 21:08:16	Alarm	12 /25/2017 21:08:16
Dispatched	12 /25/2017 21:09:42	Dispatched	12 /25/2017 21:09:42
Enroute	12 /25/2017 21:23:11	Enroute	12 /25/2017 21:10:56
Arrived	12 /25/2017 21:31:57	Arrived	12 /25/2017 21:15:36
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	12 /25/2017 22:02:17	Cleared Scene	12 /25/2017 23:15:00
In Quarters	12 /25/2017 23:18:50	In Quarters	/ / : :
In Service	12 /25/2017 22:02:17	In Service	/ / : :
Number Of People no	A	Mar derekatur (h. 1111 - Arak eritakan Makarintakan Matarintakan Markarintakan Arak eritakan dari dari dari da	The second control of the second seco

FIRE				
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False	
Area Of Fire Origin	Wall assembly, concealed wall space	Heat Source	Undetermined	
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	Abbarnador 1999-sillarmasa (1994-billarmador 1994-fillarma, con 1997-fillarmagor 1994-billar	
Type Of Material	Undetermined	Cause Of Ignition	Unintentional	
Factor Contributing To Ignition	Undetermined	unanderskelenden skeder, denderserder 🕶 Adelbelskelenderskelende in betrefen Allektiskelender about		
Human Factors Contributing	None	erationale de grande de Adrie - rémainde de décide de rémains de l'Administration de l	-communicate a communication of management of the observation of the o	

Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	1	# Of Stories Below Grade	0
Square Feet	2400	Length	— — — — — — — — — — — — — — — — — — —
Width		Floor Of Origin	1
Fire Spread	Confined to room of o	origin	
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence Of Detectors	Present	Type Of Detection System	Undetermined
Detector Power Supply	Undetermined	Detector Operation	Undetermined

PEOPLE PERSON 1			
Telephone Number	7146796736	Involvement	Caller
Name	VERIZON WIRELESS 800 451	Date of Birth	
Address	11231 CHAPMAN AVE CA 00000-		

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service
Fire Incident - What happened?	Transference of the second sec

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Acosta, Tony R	Captain	Minister hyddiddi eithir 5,450- ei gwyn Millindynn hri Mill- mae'r weddidd Japan ddidiethir ywdan Alidene	delt is restrictiveret neurhannia au unrit visita i stater anada er restri, nativez aux : nativez aux : nove a anner a delt i i GE6
Bauer, Lucas B	Engineer		GT1
Blomgren, Jason	Firefighter / Paramedic		GM1
Breneman, Jerry R	Captain		GE2
Carlson, Dave	Firefighter / Paramedic		GE2
Garcia, Drew R	Captain		GE1
Jaeger, Bill R	Firefighter		GE1
Jemiola, Jordan R	Engineer		GE2
Lindsay, Corey L	Firefighter		GT1
Lovely, Norman M	Engineer		GE6
Moore, Daniel J	Firefighter / Paramedic		GE2
Sanchez, David C	Engineer		GE1
Sawyer, Timothy	Battalion Chief		GB1
Stowe, Timothy	Firefighter / Paramedic		GM1
Strohm, Bill	Captain		GT1
Van Wie, Ryan	Paramedic / Tiller		GE6