



Garden Grove Fire Department
 Station: **G04**
 Shifts Or Platoon: **A**

Location: 12161 BAILEY ST # 4 Garden Grove CA 92640	Incident Type: 111 - Building fire
Lat/Long: N 33° 47' 9.78" W 118° 1' 55.87"	FDID: 30035 Incident #: 2018-801019 Exposure ID: 29622228 Exposure #: 0 Incident Date: 01/22/2018 Dispatch Run #: F180220227
Location Type: 1 - Street address Map Page: 797E5	

Report Completed by:	Acosta , Alberto	ID: 77	Date: 01/24/2018
Report Reviewed by:	Nguyen , Thanh	ID: 167	Date: 01/27/2018
Report Printed by:	Guardi, Lisa	ID: 4433	Date: 3/8/2018 Time: 10:53

Structure Type: Enclosed building	Property Use: 429 - Multifamily dwelling		
Automatic Extinguishment System Present: <input type="checkbox"/>	Detectors Present: <input type="checkbox"/>	Cause of Ignition: Cause under investigation	
Aid Given or Received: Mutual aid received	Primary action taken: 11 - Extinguishment by fire service personnel		
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 4		Total # of personnel on call: 11	

Narrative from dispatch:

[01/22/18 16:01:28 M007] OCFA HAS CLOSED CALL 18-008900
 [01/22/18 15:53:32 M082] GB1 GE4 - SCENE CONTACT
 [01/22/18 15:41:04 M082] INCIDENT CLOCK STOPPED: 15:41:04
 [01/22/18 15:41:00 M082] GB1 STOP THE INCIDENT CLOCK
 [01/22/18 15:40:38 M082] BAILEY IC ADV 45 MINS ON THE INCIDENT CLOCK
 [01/22/18 15:40:23 M082] INCIDENT CLOCK ACKED: 15:40:23
 [01/22/18 15:40:17 KOPS] INCIDENT CLOCK ELAPSED: 15:40:17
 [01/22/18 15:33:16 M082] GB1 INV IS OS
 [01/22/18 15:30:32 M082] RED CROSS NTFD
 [01/22/18 15:30:32 M058] BATTALION FEEDBACK EMAILED
 [01/22/18 15:30:22 M058] GCHF EMAILED/PAGED CALL
 [01/22/18 15:28:10 M082] GT1 MEDCOMM
 [01/22/18 15:28:01 M082] GB1 EXTERIOR FIRE ON A PATIO, SLIGHTLY INTERIOR ALSO, 2 DISPLACED OCCUPANTS, 2 CATS
 [01/22/18 15:25:40 M082] BAILEY IC ADV 30 MINS ON THE CLOCK
 [01/22/18 15:25:18 M082] INCIDENT CLOCK ACKED: 15:25:18
 [01/22/18 15:25:17 KOPS] INCIDENT CLOCK ELAPSED: 15:25:17
 [01/22/18 15:18:32 M082] GE5 SAFETY
 [01/22/18 15:17:26 M082] GE4 PRIMARY & SECONDARY ALL CLEAR
 [01/22/18 15:16:11 M082] GT1 ASST VENTILATIONS
 [01/22/18 15:13:52 M082] GB1 ALL CLEAR ON THE PRIMARY
 [01/22/18 15:13:37 M082] CE46 PRIMARY ALL CLEAR ON THE 2 ADJOINING UNITS
 [01/22/18 15:12:06 M082] CE17 WITH 4
 [01/22/18 15:11:36 M082] GB1 CANCEL AT2
 [01/22/18 15:11:05 M082] GE5 SC Removed
 [01/22/18 15:11:01 M082] GB1 BAILEY COMMAND
 [01/22/18 15:10:36 M082] BAILEY IC ADV 15 MINS ON THE CLOCK
 [01/22/18 15:10:22 M082] INCIDENT CLOCK ACKED: 15:10:22

[01/22/18 15:10:17 KOPS] INCIDENT CLOCK ELAPSED: 15:10:17
 [01/22/18 15:09:27 M082] CE17 WITH 4
 [01/22/18 15:09:11 M054] PAGED GB1 REGARDING STATION MOVE UP. GE7 TO STATION 5
 [01/22/18 15:08:57 M082] GT1 WITH 3
 [01/22/18 15:08:41 M082] CE48 WITH 4
 [01/22/18 15:07:15 M082] CT64 VENTILATIONS
 [01/22/18 15:07:06 M082] CT64 WITH 4
 [01/22/18 15:06:52 M082] GE5 REQ TRUCK FOR VENTILATIONS
 [01/22/18 15:06:28 M082] CE46 EXPOSURE
 [01/22/18 15:05:36 M082] CE46 CHARLIE DIV
 [01/22/18 15:05:26 M082] CE46 WITH 4
 [01/22/18 15:04:11 M082] CE65 WITH 4
 [01/22/18 15:03:42 M082] GE4 KNOCKDOWN
 [01/22/18 15:03:08 M054] PAGED GB1 OF UNITS REGARDING WF, 2ND ALARM
 [01/22/18 15:02:28 M082] GE5 BAILEY IC
 [01/22/18 15:02:24 M082] GE4 INTERIOR
 [01/22/18 15:02:20 M082] GE5 WITH 4
 [01/22/18 15:02:13 M058] HB4 PAGED TO ADVISE HUSAR42
 [01/22/18 14:59:36 M054] Updated to ALARM LEVEL 2.
 [01/22/18 14:59:30 M054] Situation Updated: 167 (STRUCTURE FIRE-WORKING)
 [01/22/18 14:59:28 M082] GE4 REQ 2ND ALARM
 [01/22/18 14:59:19 M082] GE4 WITH 3, WORKING FIRE BOTTOM UNIT, PRIMARY SEARCH
 [01/22/18 14:58:59 M087] DUPE CALLS 227 236
 [01/22/18 14:57:39 M087] DUPE CALLS 227 233
 [01/22/18 14:55:57 M007] CALL TRANSFER TO OCFA SUCCEEDED
 [01/22/18 14:55:16 M087] INCIDENT CLOCK STARTED: 14:55:16 FOR 15 MINUTES

NARRATIVE (2)

Narrative Title: n/a

Narrative Author: Ruhman, Wade

Narrative Date: 01/24/2018 11:51:56

Narrative Apparatus ID: GE4

Narrative:

GE4 GB1 CE65 GE5 CT64 RESPONDED TO STRUCTURE FIRE RESIDENTIAL. GE4 ARRIVED ON SCENE OF A 2 STORY APARTMENT COMPLEX WITH A WORKING FIRE SHOWING FROM A LOWER UNIT. GE4 WENT INTO ATTACK MODE, INITIATED A PRIMARY SEARCH, WAS ABLE TO SECURE ITS OWN WATER SUPPLY, ASSIGNED SECOND DUE TO TAKE COMMAND AND BALANCED THE RESPONSE TO A SECOND ALARM. WE USED A PRECONNECT LINE TO CONFINE AND EXTINGUISH THE FIRE. GE4 WAS ASSIGNED INTERIOR AND WAS ABLE TO REMOVE 2 CATS FROM THE PREMISE DURING THE PRIMARY SEARCH. SECONDARY SEARCH WAS ALL CLEAR. EXTERIOR AND INTERIOR WALLS WERE EXPOSED TO CHECK FOR EXTENSION WHICH WAS NEGATIVE. OVERHAUL AND INVESTIGATION WAS PERFORMED IN CONJUNCTION WITH GT1 AND WILL PROVIDE A REPORT ON FINDINGS. ELECTRICITY TO THE INVOLVED UNIT WAS ISOLATED AND SHUT OFF. THE INVOLVED UNITS OCCUPANTS WERE DISPLACED, 3 OTHER REMAINING UNITS WERE ALLOWED TO OCCUPY THEIR RESIDENCES AFTER THE INCIDENT. BUILDING OWNER WAS ON SCENE, WAS GIVEN AND SIGNED THE PROPERTY RELEASE. GE4 AWAITED RED CROSS ARRIVAL AND RELEASED THE BUILDING BACK TO THE PROPERTY OWNER AND OCCUPANTS. GE4 COMPLETE.

PROPERTY OWNER:

MARDEE BALLEW

2409 HILLTOP CT

FULLERTON CA 92835

714-323-3416

NARRATIVE (3)**Narrative Title:** capt**Narrative Author:** Acosta, Alberto**Narrative Date:** 01/22/2018 21:26:55**Narrative Apparatus ID:** GE5**Narrative:**

Ge5 responded to a structure fire residential. when arrived on scene, Ge5 assumed command. Assigned my crew to ge4 interior. assigned ce65 charlie div. ct64 was assigned vent group. ce46 was assigned exposure group. command was released to gb1 when he arrived on scene.

NARRATIVE (4)**Narrative Title:** FIRE**Narrative Author:** Strohm, Bill**Narrative Date:** 01/22/2018 20:45:12**Narrative Apparatus ID:** GT1**Narrative:**

GT1 ASSISTED OCFA TRUCK WITH VENTILATION. GT1 PREFORMED OVERHAUL. GT1 CONDUCTED AND ORGIN AND CAUSE INVESTIGATION. WITNESS STATEMENTS AND SCENE EXAMINATION REVEALED THAT THE AREA OF ORIGIN WAS THE REAR PATIO EXTERIOR WALL, ADJACENT TO THE KITCHEN WINDOW AND THE GLASS SLIDING DOOR. THIS WAS AN ACCIDENTAL TYPE FIRE DUE TO IMPROPER DISPOSAL OF SMOKING MATERIAL.

CAPTAIN STROHM

NARRATIVE (5)**Narrative Title:** RESIDENTIAL STRUCTURE**Narrative Author:** Sawyer, Timothy**Narrative Date:** 01/24/2018 13:52:23**Narrative Apparatus ID:** GB1**Narrative:**

THIS WAS A 2 STORY APT BUILDING WITH 4 UNITS. FIRE WAS ON THE OUTSIDE PATIO AND EXTENDED INTO THE KITCHEN ARE OF THE APARTMENT.

GB1 TRANSFERRED COMMAND FROM GE5 CAPT A.ACOSTA WHO HAD ASSIGNED 1ST ALARM UNITS. CAPT ACOSTA WAS ASSIGNED SAFETY, DID 360 OF SCENE AND REPORTED BACK. GT1 WAS ASSIGNED TO VENT GROUP (CT64) TO ASSIST W/ HORIZONTAL VENT ON AFFECTED UNITS. FIRE WAS KNOCKED DOWN, PRIMARY AND SECONDARY WERE COMPLETED IN ALL UNITS. GI-1 INVESTIGATED, RED CROSS CALLED FOR 2 ADULTS AND 3 ANIMALS. SCENE WAS LEFT TO GE4 AND GT1 WHO COMPLETED OVERHAUL, PROPERTY RELEASE AND INSTRUCTIONS TO BUILDING OWNER.

APPARATUS			
Fire Controlled Date / Time:		1/22/2018 4:33:24 PM	
Unit	GB1	Unit	GE4
Type:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	()	Response Mode:	()
# of People	1	# of People	3
Alarm	01 /22/2018 14:54:17	Alarm	01 /22/2018 14:54:17
Dispatched	01 /22/2018 14:55:16	Dispatched	01 /22/2018 14:55:16
Enroute	01 /22/2018 14:57:58	Enroute	01 /22/2018 14:57:36
Arrived	01 /22/2018 15:08:01	Arrived	01 /22/2018 14:59:43
Cancelled	-- /-- /-- -- :-- :--	Cancelled	-- /-- /-- -- :-- :--
Cleared Scene	01 /22/2018 16:15:00	Cleared Scene	01 /22/2018 16:33:24
In Quarters	-- /-- /-- -- :-- :--	In Quarters	01 /22/2018 16:33:24
In Service	-- /-- /-- -- :-- :--	In Service	01 /22/2018 16:33:24
Unit	GE5	Unit	GT1
Type:	Engine	Type:	Truck or aerial
Use:	Suppression	Use:	Suppression
Response Mode:	()	Response Mode:	Lights and Sirens
# of People	4	# of People	3
Alarm	01 /22/2018 14:54:17	Alarm	01 /22/2018 14:54:17
Dispatched	01 /22/2018 14:55:16	Dispatched	01 /22/2018 14:55:16
Enroute	01 /22/2018 14:56:11	Enroute	01 /22/2018 14:56:55
Arrived	01 /22/2018 15:02:38	Arrived	01 /22/2018 15:08:58
Cancelled	-- /-- /-- -- :-- :--	Cancelled	-- /-- /-- -- :-- :--
Cleared Scene	01 /22/2018 15:02:40	Cleared Scene	01 /22/2018 16:33:00
In Quarters	-- /-- /-- -- :-- :--	In Quarters	-- /-- /-- -- :-- :--
In Service	-- /-- /-- -- :-- :--	In Service	-- /-- /-- -- :-- :--
Number Of People not on apparatus: 0			

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Exterior balcony, unenclosed porch	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause under investigation
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	None		

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	2	# Of Stories Below Grade	0
Square Feet	600	Length	
Width		Floor Of Origin	1
Fire Spread	Confined to room of origin		
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0

ARSON		
Agency Name	Agency Address	Agency Phone
	Bailey St	
Remarks:		
Type: Accidental fire.		
Area of Origin: Back patio, exterior wall adjacent to the kitchen window and glass sliding door.		
Cause: Improper disposal of smoking material.		

PEOPLE -- PERSON 1			
Telephone Number	7144573029	Involvement	Caller
Name	SPRINT 800-877-7330 OPT 1	Date of Birth	
Address	11861 VALLEY VIEW ST GARDEN GROVE, CA 92845-		

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service
Fire Incident - What happened?	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Crawford, Timothy A	Engineer		GE4
Feldman, Joshua A	Firefighter / Paramedic		GE4
Ruhman, Wade E	Captain		GE4
Sawyer, Timothy	Battalion Chief		GB1

Member Making Report (Captain Alberto Acosta): _____

Supervisor (Captain Thanh Nguyen): _____

