

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1506153  
Exposure Number: 00  
Multi-Agency IC#:   
Incident Date: 05/30/15  
Dispatch Time: 06:36:16  
Arrival Time: 06:43:32  
Controlled Time:   
Ending Time: 07:39:45  
First-In Company: GE5  
District: G2114  
Incident Type: Water problem, other  
Mutual Aid: None  
Method of Alarm: Telephone  
Type of Weather:   
Air Temperature: 61  
Address, CSZ: 11330 MARKON DR  
Census Tract:   
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Shut down system  
Actions Taken 2:   
Actions Taken 3:   
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 0  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 1  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury:   
Non-FS Fatal:

## PROPERTY &amp; STUDIES

Property Losses:   
Content Losses:   
Property Value:   
Contents Value:   
Insurance Co:   
Building Ins:   
Mixed Prop Use:   
Property Use: Manufacturing, processing  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## COMMENTS

\*\*\*\*\* GE5 \*\*\*\*\*

SERVICE-INVESTIGATION  
ENCOUNTERED A SPRINKLER ACTIVATION IN A FURNITURE WAREHOUSE/WOODSHOP DUE TO A POSSIBLE TABLESAW/EQUIPMENT FIRE OUT P.T.A. GE5 SHUT DOWN THE SPRINKLER SYSTEM AND SECURED THE PROPERTY AFTER MULTIPLE ATTEMPTS TO CONTACT THE BUSINESS OWNER BY G.G.P.D. AND GE5 FAILED. (PHONE WAS NOT ANSWERED). ADJACENT BUSINESS WAS ADVISED TO NOTIFY THE SPRINKLER CO. TO RESPOND TO PUT THE SYSTEM BACK IN SERVICE BEFORE CONTINUING OPERATIONS. NO ALARM CO. WAS MONITORING THE SYSTEM. GE5, G.G.P.D., AND PUBLIC WORKS DEPT. ALL SECURED AFTER COMPLETION. CAPT. EDNOFF