

INCIDENT REPORT

INCIDENT

Fire Department: Garden Grove Fire Department
Incident Number: G1504165
Exposure Number: 00
Multi-Agency IC#:
Incident Date: 04/11/15
Dispatch Time: 00:10:46
Arrival Time: 00:16:32
Controlled Time: 00:26:24
Ending Time: 02:56:03
First-In Company: GE1
District: G2524
Incident Type: Building fire
Mutual Aid: None
Method of Alarm: E911
Type of Weather:
Air Temperature: 55
Address, CSZ: 12212 QUARTZ CI
Census Tract:
Fire Haz Sev Zone: Medium

RESOURCES & CASUALTIES

Actions Taken 1: Extinguishment by fire service personnel
Actions Taken 2: Salvage & overhaul
Actions Taken 3:
#Apparatus Resp Engine: 0
#Apparatus Resp Trk: 1
#Apparatus Resp Med: 1
#Apparatus Resp Oth: 4
Fire Svs Injury: 0
Fire Svs Fatal: 0
Non-FS Injury: 0
Non-FS Fatal: 0

PROPERTY & STUDIES

Property Losses: \$10,000
Content Losses: \$10,000
Property Value:
Contents Value:
Insurance Co:
Building Ins:
Mixed Prop Use:
Property Use: Parking garage, (detached residential ga
Detector

INCIDENT REPORT

Hazmat Rel: None
Critical Inc:
Special Studies:

FIRE/ EXPLOSION SITUATION

Residential Units:
Bldgs. Involved:
Acres Burned:
On-Site Mat/Stor: Lumber, sawn wood
Area of Origin: Vehicle storage area; garage, carport
Heat Source: Spontaneous combustion, chemical reactio
First Item: Oily rags
Confined to Object:
Material Type:
Factor Causing: Unintentional
Contributing Factors 1: Improper container or storage procedure
Contributing Factors 2: Abandoned or discarded materials or products
Human Factor Cont 1: Unattended or unsupervised person
Human Factor Cont 2:
Human Factor Cont 3:
Age
Sex
Equip Involved: None
Equip Brand:
Equip Model:
Equip Serial Number:
Equip Year:
Equip Power Source:
Equip Portability:
Mobile Prop Inv:
Mobile Prop Type:
Mobile Prop Make:
Mobile Prop Model:
Mobile Prop Year:
Mobile Prop Lic. Plate:
Mobile Prop Lic. State:
Mobile Prop VIN Number:
Mobile Prop Stolen?:
Suppression Factors:

STRUCTURE FIRE

Type:
Status: Enclosed building
St Above Grnd: Occupied and operating
St Below Grnd: 1

INCIDENT REPORT

Main Floor Size: 0
Fire Origin: 800
Extent of Flame: Vehicle storage area; garage, carport
Number of Stories Damage: Confined to room of origin
Minor:
Sign:
Heavy;
Extreme:
Auto Ext Sys: None Present
AES Type:
AES Operation:
Sprinkler Heads:
AES Failure Reason:
Detectors: Not present
Detector Type:
Det. Power Supply:
Det. Operation:
Det. Effectiveness:
Det. Failure Reason:

COMMENTS

***** GE1 *****

FIRE

GE1 RESPONDED TO A STRUCTURE FIRE AND FOUND A DETACHED GARAGE THAT HAD LIGHT SMOKE SHOWING FROM EVE LINE OF THE STRUCTURE. GE1 ATTACKED THE SMALL CONTENTS FIRE. GE1 GT1 COMPLETED OVERHAUL. GE1 RELEASED THE SCENE BACK TO THE PROPERTY OWNER (PROPERTY RELEASE FORM SIGNED).

CAPTAIN STROHM