

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1507030  
Exposure Number: 00  
Multi-Agency IC#:   
Incident Date: 06/21/15  
Dispatch Time: 13:30:58  
Arrival Time: 13:34:27  
Controlled Time:   
Ending Time: 13:45:27  
First-In Company: GE4  
District: G2311  
Incident Type: Passenger vehicle fire  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:   
Air Temperature: 79  
Address, CSZ: 5831 RICHMOND AV  
Census Tract:   
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Investigate fire out on arrival  
Actions Taken 2: Investigate  
Actions Taken 3: Refer to proper authority  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 0  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 1  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$10,000  
Content Losses: \$0  
Property Value:   
Contents Value:   
Insurance Co:   
Building Ins:   
Mixed Prop Use:   
Property Use: None  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved:  
Acres Burned:  
On-Site Mat/Stor: None  
Area of Origin Engine area, running gear, wheel area  
Heat Source: Undetermined  
First Item: Undetermined  
Confined to Object:  
Material Type:  
Factor Causing: Cause undetermined after investigation  
Contributing Factors 1: None  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: None  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source:  
Equip Portability:  
Mobile Prop Inv: Involved in ignition and burned  
Mobile Prop Type: Automobile, passenger car, ambulance, ra  
Mobile Prop Make: Mercedes Benz  
Mobile Prop Model: SL 500  
Mobile Prop Year: 2003  
Mobile Prop Lic. Plate: 7GCL516  
Mobile Prop Lic. State:  
Mobile Prop VIN Number: WDBSK75F63FO23789  
Mobile Prop Stolen?:  
Suppression Factors: None

## STRUCTURE FIRE

Type:  
Status:  
# St Above Grnd:  
# St Below Grnd:

## INCIDENT REPORT

-----  
Main Floor Size:  
Fire Origin:  
Extent of Flame: Engine area, running gear, wheel area  
Number of Stories Damaged By Flame  
Minor:  
Sign:  
Heavy;  
Extreme:  
Auto Ext Sys:  
AES Type:  
AES Operation:  
# Sprinkler Heads:  
AES Failure Reason:  
Detectors:  
Detector Type:  
Det. Power Supply:  
Det. Operation:  
Det. Effectiveness:  
Det. Failure Reason:  
-----

## COMMENTS

-----  
\*\*\*\*\* GE4 \*\*\*\*\*

## FIRE/VEHICLE

GE4 ARRIVED TO A CAR FIRE OUT ON ARRIVAL. FIRE WAS INVESTIGATED, REPORT WAS TAKEN, AND INFO GATHERED.

CAPT T SAWYER