



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #354722

Service Request: 354722

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: April 03, 2013 10:10AM

Requester: HOLMON

Home Phone:

Work Phone:

Other Phone:

Created by: lorianah

Request: NPDES INDUSTRIAL INSPECTION OF PT GUNWORKS

Location: 11711 MONARCH ST, SUITE

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

Note #1 (04/03/13 by lorianah): NO VIOLATIONS. ONE MACHINE TO MFR GUN PARTS. NO COOLANT OR HAZ MAT. ONLY SMALL AMOUNT OF METAL SHAVINGS THAT WILL BE STORED INSIDE IN A DRUM AND TAKEN TO RECYCLE DAILY.

Task #1

Status: CLOSED on April 03, 2013 12:00AM by Loriana Hornik

Description: NPDES INDUSTRIAL INSPECTION OF PT GUNWORKS

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Loriana Hornik

ECD: April 3, 2013

Actions: C LOW PRIORITY, 115.10 EXPLAINED NPDES POLICIES, 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.12 COMPLETED INSPECTION FORM, 115.16 BMP FULLY IMPLEMENTED, 115.2 INDUSTRIAL



GARDEN GROVE PUBLIC WORKS DEPARTMENT
SERVICE REQUEST #327583

Service Request: 327583

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: December 12, 2011 07:59AM

Requester: HOLMON

Home Phone:

Work Phone:

Other Phone:

Created by: allens

Request: NPDES INDUSTRIAL INSPECTION OF SYNERTECH P/M TECH

Location: 11711 MONARCH ST,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

File attachments: 2

Note #1 (12/12/11 by allens): Met with Kevin Barre, advised of policies, advised to cover up or move inside rusty metals outside, dispose of paint properly that are stored outside, monitor outside perimeter of business for general good housekeeping.

Task #1

Status: CLOSED on December 12, 2011 07:59AM by Allen Serna

Description: NPDES INDUSTRIAL INSPECTION OF SYNERTECH P/M TECH

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Allen Serna

ECD:

Actions: B MEDIUM PRIORITY, 115.10 EXPLAINED NPDES POLICIES, 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.12 COMPLETED INSPECTION FORM, 115.15 OTHER (SEE COMMENTS), 115.17 BMP PARTIALLY IMPLEMENTED, 115.2 INDUSTRIAL



GARDEN GROVE PUBLIC WORKS DEPARTMENT
SERVICE REQUEST #275658

Service Request: 275658

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: July 09, 2009 05:03PM

Requester: HOLMON

Home Phone:

Work Phone: 5956

Other Phone:

Created by: lorianah

Request: NPDES INDUSTRIAL INSPECTION AT SYNERTECH PM

Location: 11711 MONARCH ST,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

Note #1 (07/18/09 by None): OIL SPILLED ON GROUND AND WASTE OIL IN CONTAINER NOT DISPOSED OF PROPERLY. SOME METALS OUTSIDE THAT NEED TO BE DISPOSED OF OR COVERED UP.

Note #2 (03/01/10 by SYSTEM): Completed by: LH

Task #1

Status: CLOSED on July 09, 2009 12:00PM by LH

Description: Assigned to LH

Category: 115 NPDES INSPECTION

Division:

Completed by:

Assigned to:

Requester contacted:

ECD:

Actions: B MEDIUM PRIORITY, 115.10 EXPLAINED NPDES POLICIES, 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.12 COMPLETED INSPECTION FORM, 115.17 BMP PARTIALLY IMPLEMENTED, 115.2 INDUSTRIAL