

## INCIDENT REPORT

## INCIDENT

Fire Department: Garden Grove Fire Department  
Incident Number: G1601734  
Exposure Number: 00  
Multi-Agency IC#: 16-017072  
Incident Date: 02/14/16  
Dispatch Time: 09:43:03  
Arrival Time: 09:48:58  
Controlled Time:  
Ending Time: 10:33:20  
First-In Company: GE7  
District: G2620  
Incident Type: Outside equipment fire  
Mutual Aid: None  
Method of Alarm: E911  
Type of Weather:  
Air Temperature: 56  
Address, CSZ: 10302 TRASK AV  
Census Tract:  
Fire Haz Sev Zone: Medium

## RESOURCES &amp; CASUALTIES

Actions Taken 1: Investigate  
Actions Taken 2: Refer to proper authority  
Actions Taken 3:  
#Apparatus Resp Engine: 0  
#Apparatus Resp Trk: 1  
#Apparatus Resp Med: 0  
#Apparatus Resp Oth: 3  
Fire Svs Injury: 0  
Fire Svs Fatal: 0  
Non-FS Injury: 0  
Non-FS Fatal: 0

## PROPERTY &amp; STUDIES

Property Losses: \$0  
Content Losses: \$0  
Property Value:  
Contents Value:  
Insurance Co:  
Building Ins:  
Mixed Prop Use:  
Property Use: Mercantile, business, other  
Detector

## INCIDENT REPORT

Hazmat Rel: None  
Critical Inc:  
Special Studies:

## FIRE/ EXPLOSION SITUATION

Residential Units:  
Bldgs. Involved:  
Acres Burned:  
On-Site Mat/Stor: None  
Area of Origin: Conduit, pipe, utility, or ventilation shaft  
Heat Source: Electrical arcing  
First Item: Electrical wire, cable insulation  
Confined to Object:  
Material Type:  
Factor Causing: Failure of equipment or heat source  
Contributing Factors 1: Electrical failure, malfunction, other  
Contributing Factors 2:  
Human Factor Cont 1: None  
Human Factor Cont 2:  
Human Factor Cont 3:  
Age  
Sex  
Equip Involved: Electric meter, meter box  
Equip Brand:  
Equip Model:  
Equip Serial Number:  
Equip Year:  
Equip Power Source: Electrical, other  
Equip Portability: Stationary  
Mobile Prop Inv:  
Mobile Prop Type:  
Mobile Prop Make:  
Mobile Prop Model:  
Mobile Prop Year:  
Mobile Prop Lic. Plate:  
Mobile Prop Lic. State:  
Mobile Prop VIN Number:  
Mobile Prop Stolen?:  
Suppression Factors:

## COMMENTS

\*\*\*\*\* GE7 \*\*\*\*\*

FIRE STRUCTURE FIRE COMMERCIAL

GE7 ON SCENE OF

INCIDENT REPORT

---

A ONE STORY COMMERCIAL TILT-UP WITH A FLAT ROOF TO FIND LIGHT SMOKE/SMALL FIRE FROM AN ELECTRICAL METER TO THE EAST SIDE OF THE EXTERIOR OF THE STRUCTURE. GE7 IN AN INVESTIGATIVE MODE. GE7 REQUESTED EDISON TO RESPOND TO THE SCENE. GE7 AND GT1 MADE ENTRY INTO THE UNIT ADJACENT TO THE ELECTRICAL METER TO FIND THE WALL OPPOSITE OF THE METER COLD AND WITH NO INVOLVMENT OR SMOKE IN THE INTERIOR OF THAT UNIT. UNIT OCCUPANT WAS ON SCENE AND PROVIDED ENTRY; NO FORCIBLE ENTRY WAS NEEDED. SMOKE/FIRE TO THE EXTERIOR ELECTRICAL METER EVENTUALLY WENT OUT WITH NO EXTINGUISHMENT FROM FIRE PERSONNEL NEEDED. BALANCE OF THE ASSIGNMENT WAS RELEASED AND GB1 AND GE7 REMAINED ON SCENE. GB1 DISSOLVED COMMAND AND GE7 REMAINED ON SCENE FOR THE ARRIVAL OF EDISON. EDISON ARRIVED ON SCENE AND METRO NET WAS NOTIFIED. SCENE RELEASED TO EDISON. GE7 COMPLETED.

CAPTAIN BRENEMAN