



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #393080

Service Request: 393080
Department: Public Works
Status: CLOSED
Priority: HIGH
Created at: June 17, 2015 11:20AM

Requester: Holmon
Home Phone:
Work Phone: 741-5956
Other Phone:
Created by: allens

Request: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Location: 7100 CHAPMAN AVE, ALSO 12570 KNOTT

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

File attachments: 1

Note #1 (06/17/15 by allens): Met with Linda Shaffer, completed site inspections at both facilities, no violations

Task #1

Status: CLOSED **Status changed:** June 17, 2015 11:20AM

Description: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Category: 115 NPDES INSPECTION **Assigned to:** Albert Holmon III

Division: ENVIRONMENTAL COMP **Requester contacted:** _____

Completed by: Allen Serna **Date completed:** _____ **ECD:** _____

Actions: A, 115.10, 115.11, 115.12, 115.15, 115.16, 115.2

Comments:

Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #375009

Service Request: 375009
Department: Public Works
Status: CLOSED
Priority: HIGH
Created at: May 07, 2014 08:17AM

Requester: Holmon
Home Phone:
Work Phone: 741-5956
Other Phone:
Created by: allens

Request: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES COMPANY

Location: 7100 CHAPMAN AVE, ALSO 12570 KNOTT ST

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

File attachments: 1

Note #1 (05/07/14 by allens): Met with Daryl Pease & Yenny Khuu, advised of City's policies & NPDES regulations, no violations at this site

Task #1

Status: CLOSED **Status changed:** May 07, 2014 08:17AM

Description: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Category: 115 NPDES INSPECTION **Assigned to:** Albert Holmon III

Division: ENVIRONMENTAL COMP **Requester contacted:** _____

Completed by: Allen Serna **Date completed:** _____ **ECD:** _____

Actions: A, 115.10, 115.11, 115.12, 115.15, 115.16, 115.2

Comments:


Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #355803

Service Request: 355803
Department: Public Works
Status: CLOSED

Requester: HOLMON
Home Phone:
Work Phone:

Priority: NORMAL
Created at: April 23, 2013 12:00AM

Other Phone:
Created by: lorianah

Request: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Location: 7100 CHAPMAN AVE,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

File attachments: 10

Note #1 (04/23/13 by lorianah): OILY OR RUSTED EQUIPMENT STORED OUTAIDE WITH OUT COVER. OILY CONDENSATE BUCKED OVERFLOWING INTO SWALE. OIL LEAKING FROM SLUDGE BINS COLLECTED THROUGHOUT THE SITE. NEED TO IMPROVE HOUSE KEEPING OF LITTER AND SPILL RESPONSE.

Task #1

Status: CLOSED **Status changed:** April 23, 2013 12:00AM

Description: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Category: 115 NPDES INSPECTION **Assigned to:** Albert Holmon III

Division: ENVIRONMENTAL COMP **Requester contacted:** _____

Completed by: Loriana Hornik **Date completed:** _____ **ECD:** April 23, 2013

Actions: A, 115.10, 115.11, 115.12, 115.17, 115.2, 130.10

Comments:


Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #330332

Service Request: 330332
Department: Public Works
Status: CLOSED
Priority: NORMAL
Created at: February 01, 2012 05:24PM

Requester: Holmon
Home Phone:
Work Phone:
Other Phone:
Created by: devinf

Request: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Location: 7100 CHAPMAN AVE,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

File attachments: 3

Note #1 (02/01/12 by devinf): Clean oil residue from outside area and in swale. Clean unknown white chalky substance from outside green container.

Task #1

Status: CLOSED **Status changed:** February 01, 2012 05:24PM

Description: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Category: 115 NPDES INSPECTION **Assigned to:** Albert Holmon III

Division: ENVIRONMENTAL COMP **Requester contacted:** _____

Completed by: Maria Alcaraz **Date completed:** _____ **ECD:** February 1, 2012

Actions: A, 115.10, 115.11, 115.12, 115.17, 115.2

Comments:


Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



**GARDEN GROVE PUBLIC WORKS DEPARTMENT
SERVICE REQUEST #311394**

Service Request: 311394
Department: Public Works
Status: CLOSED
Priority: NORMAL
Created at: March 21, 2011 04:46PM

Requester: HOLMON
Home Phone:
Work Phone:
Other Phone:
Created by: lorianah

Request: FOLLOW UP NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Location: 7100 CHAPMAN AVE,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

Note #1 (03/21/11 by lorianah): MET WITH KEITH PETTUS. NO VIOLATIONS. ALL MATERIALS THAT ARE STORED OUTSIDE ARE COVERED, NO LEAKING EQUIPMENT ON SOUTH SIDE OF BUILDING, ALL RAIN WATER IN LOADING DOCK IS PUMPED INTO A TOTE AND SEND OUT AS HAZ WASTE.

Task #1

Status: CLOSED **Status changed:** March 21, 2011 04:46PM

Description: FOLLOW UP NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Category: 115 NPDES INSPECTION **Assigned to:** Albert Holmon III

Division: ENVIRONMENTAL COMP **Requester contacted:** _____

Completed by: Loriana Hornik **Date completed:** _____ **ECD:** March 21, 0011

Actions: A, 115.10, 115.11, 115.12, 115.16, 115.2

Comments:


Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #307850

Service Request: 307850
Department: Public Works
Status: CLOSED
Priority: NORMAL
Created at: January 19, 2011 09:10AM

Requester: HOLMON
Home Phone:
Work Phone:
Other Phone:
Created by: lorianah

Request: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Location: 7100 CHAPMAN AVE,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

File attachments: 2

Note #1 (01/19/11 by lorianah): FLUID LEAKING FROM EQUIPMENT STORED OUTSIDE, EXTENSIVE EXISTING STAINING THROUGHOUT THE SITE, LARGE WHITE STAIN AND OIL STAINING IN LOADING DOCK .

Task #1

Status: CLOSED **Status changed:** January 20, 2011 09:10AM

Description: NPDES INDUSTRIAL INSPECTION OF AIR INDUSTRIES CORPORATION

Category: 115 NPDES INSPECTION **Assigned to:** Albert Holmon III

Division: ENVIRONMENTAL COMP **Requester contacted:**

Completed by: Loriana Hornik **Date completed:** **ECD:** January 19, 2011

Actions: A, 115.10, 115.11, 115.12, 115.17, 115.2

Comments:

Other comments:

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #293863

Service Request: 293863
Department: Public Works
Status: CLOSED

Requester: HOLMON
Home Phone:
Work Phone:
Other Phone:
Created by: lorianah

Priority: NORMAL
Created at: May 20, 2010 12:00AM

Request: NPDES ANNUAL INDUSTRIAL INSPECTION OF AIR INDUSTRIES

Location: 7100 CHAPMAN AVE,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

File attachments: 5

Note #1 (05/20/10 by lorianah): MET WITH WARREN SEVILLA. OIL SPILLED FROM AIR COMPRESSOR, OIL WATER TANK AND FILTERING UNIT.

Task #1

Status: CLOSED **Status changed:** May 20, 2010 12:00AM

Description: NPDES ANNUAL HIGH PRIORITY INSPECTION AT AIR INDUSTRIES

Category: 115 NPDES INSPECTION **Assigned to:** Albert Holmon III

Division: ENVIRONMENTAL COMP **Requester contacted:** _____

Completed by: Loriana Hornik **Date completed:** _____ **ECD:** May 20, 0010

Actions: A, 115.10, 115.11, 115.12, 115.17, 115.2

Comments:

Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #271175

Service Request: 271175

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: April 13, 2009 04:41PM

Requester: HOLMON

Home Phone:

Work Phone: 5956

Other Phone:

Created by: LORIANAH

Request: NPDES ANNUAL INDUSTRIAL INSPECTION OF AIR INDUSTRIES

Location: 7100 CHAPMAN AVE,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

Note #1 (07/18/09 by None): OIL LEAKING OUT OF BERMED AREA BECAUSE EMPLOYEE SERVICING MACHINE: SURING SERVICING THEY REMOVE AN OIL FILTER AND SOME OF THE OIL LEAKS OUT OF THE BERMED AREA ON TO THE ASHPALT IN THE BACK OF THE FACILITY.
Note #2 (03/01/10 by SYSTEM): Completed by: LH

Task #1

Status: CLOSED **Status changed:** April 13, 2009 12:00PM

Description: Assigned to LH

Category: 115 NPDES INSPECTION **Assigned to:** _____

Division: _____ **Requester contacted:** _____

Completed by: _____ **Date completed:** _____ **ECD:** _____

Actions: A, 115.10, 115.11, 115.12, 115.17, 115.2

Comments:

Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #256279

Service Request: 256279
Department: Public Works
Status: CLOSED
Priority: NORMAL
Created at: May 19, 2008 04:28PM

Requester: HOLMON
Home Phone:
Work Phone: 5956
Other Phone:
Created by: LORIANAH

Request: NPDES INSPECTION OF AIR INDUSTRIES, FOLLOWING A COMPLAINT

Location: 7100 CHAPMAN AVE,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

Note #1 (07/18/09 by None): EXCESSIVE AMOUNTS OF CONDENSATE FLOWING OFFSITE FROM THEIR COOLING SYSTEM. tHERE ARE OIL SPILLS THROUGHOUT THE EXTERIOR OF THE FAICLITY, 55 GALLON WASTE OIL DRUMS STORED OUTSIDE WITHOUT CONTAINMENT OR EVEN CAPS ON THE OPENINGS OF THE DRUMS, TRASH AND DEBRIS THROUGHOUT THE EAST SIDE OF THE FACILITY. 5/20/08: I SPOKE TO MR. BOB CHADOWITZ FROM OCSD IN REGARD TO PLUMBING THE CONDENSATE TO THE SEWER SYSTEM, AND HE SAID THAT HE DOES NOT BELIEVE IT WILL BE A PROBLEM AND THE FACILITY WILL NOT NEED TO GET A PERMIT.

Note #2 (03/01/10 by SYSTEM): Completed by: LH

Task #1

Status: CLOSED **Status changed:** May 19, 2008 12:00PM

Description: Assigned to LH

Category: 115 NPDES INSPECTION **Assigned to:** _____

Division: _____ **Requester contacted:** _____

Completed by: _____ **Date completed:** _____ **ECD:** _____

Actions: A, 115.10, 115.11, 115.12, 115.17, 115.2

Comments:


Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #242300

Service Request: 242300
Department: Public Works
Status: CLOSED

Requester: HOLMON
Home Phone:
Work Phone: 5956
Other Phone:
Created by: apadilla

Priority: NORMAL
Created at: August 08, 2007 09:20AM

Request: ANNUAL INDUSTRIAL INSPECTION OF AIR INDUSTRIES

Location: 7100 CHAPMAN AVE,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

Note #1 (07/18/09 by None): MET WITH BILL NEWMAN. HE INDICATED THAT THE METALS ARE OUTSIDE BCAUSE HE IS WAITING FOR CITY TO APPROVE THE CONSTRUCTION OF COVERED STORAGE AREA. I LEFT A MESSAGE FOR BILL INDICATING THAT PW-ECD HAS APPROVED HIS PLANS AND THAT HE NEEDED TO FOLLOW UP WITH CITY HALL. REQUIRED TO COVER METAL PARTS AND CLEAN OILY ASPHALT AREA ON WEST SIDE. ALGAE ON CITY GUTTERS MUST ALSO BE CLEANED. WDID HAS BEEN UPDATED.

Task #1

Status: CLOSED **Status changed:** August 08, 2007 12:00PM

Description: Assigned to HOLMON

Category: 115 NPDES INSPECTION **Assigned to:** _____

Division: _____ **Requester contacted:** _____

Completed by: _____ **Date completed:** _____ **ECD:** _____

Actions: A, 115.10, 115.12, 115.17, 115.2

Comments:


Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #241719

Service Request: 241719
Department: Public Works
Status: CLOSED
Priority: NORMAL
Created at: July 25, 2007 11:25AM

Requester: Steve Porras
Home Phone:
Work Phone: 714-741-5375
Other Phone:
Created by: allens

Request: Condensation from Air Conditioner Unit coming from hose flowing into street (DE)

Location: 7100 CHAPMAN AVE, Air Industries

Public Property: YES
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

Note #1 (07/18/09 by None): Spoke with Pat, advised of City Policys, gave business card to schedule inspection. Water was coming from A/C Unit, water was clear, nut observed algae in gutter, need to test ph during next visit.

Note #2 (03/01/10 by SYSTEM): Completed by: ALLEN SERNA

Task #1

Status: CLOSED **Status changed:** July 25, 2007 02:00AM

Description: Assigned to

Category: 130 NPDES VIOLATION (AUTO- **Assigned to:** _____

Division: _____ **Requester contacted:** _____

Completed by: _____ **Date completed:** _____ **ECD:** _____

Actions: 115.10, 115.2

Comments:

Other comments: _____

Labor Costs

Name	Reg	OT	Total
Allen Serna	0 hours	0 hours	\$ 0.00
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
TOTAL		\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #217504

Service Request: 217504

Requester: PADILLA

Department: Public Works

Home Phone:

Status: CLOSED

Work Phone: 5564

Priority: NORMAL

Other Phone:

Created at: August 25, 2005 04:45PM

Created by: apadilla

Request: EXCESSIVE AMT OF WATER COMING FROM STORM SWALE AT AIR INDUSTRIES

Location: 7100 CHAPMAN AVE,

Public Property: YES

Eng. Permit:

Square Feet:

Police Num.:

Fire Num.:

Note #1 (07/18/09 by None): WATER IS CLEAN, JUST EXCESSIVE AMOUNT COMING FROM BACK AREA - GATES ARE LOCKED.

EMPLOYEE DID NOT PROVIDE ACCESS; PER EMPLOYEE, HE CONTACTED HIS MAINTENANCE CREW TO MAKE SURE IT'S NOT WATER PIPE BUT IT APPEARS THAT THE WATER IF FROM FIRE SPRINKLERS.

Note #2 (03/01/10 by SYSTEM): Completed by: AP

Task #1

Status: CLOSED **Status changed:** August 25, 2005 12:00PM

Description: Assigned to HOLMON

Category: 130 NPDES VIOLATION (AUTO- **Assigned to:** _____

Division: _____ **Requester contacted:** _____

Completed by: _____ **Date completed:** _____ **ECD:** _____

Actions: 130.4, 130.13

Comments:

Other comments: _____

Labor Costs

Name	Reg	OT	Total
	0 hours	0 hours	\$ 0.00
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #147224

Service Request: 147224
Department: Public Works
Status: CLOSED

Requester: COUNTY OF ORANGE
Home Phone:
Work Phone:
Other Phone:
Created by: TERIL

Priority: NORMAL
Created at: November 16, 1998 03:57PM

Request: WASTE CUTTING OIL SPILL

Location: 7100 CHAPMAN AVE, AIR INDUSTRIES CORP.

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

Note #1 (03/01/10 by SYSTEM): Completed by: O.C. COUNTY

Task #1

Status: CLOSED **Status changed:** November 17, 1998 12:00PM

Description: Assigned to YASUTAKE

Category: 330 NPDES VIOLATION **Assigned to:** _____

Division: STREET MAINT **Requester contacted:** _____

Completed by: _____ **Date completed:** _____ **ECD:** _____

Actions: 330.8

Comments:

Other comments: _____

Labor Costs

Name	Reg	OT	Total
TOTAL	0 hours	0 hours	\$ 0.00

Equipment/Material Costs

Num	Description	Cost
1		
2		
	TOTAL	\$ 0.00