INCIDENT REPORT

_____ INCIDENT ______ Fire Department: Garden Grove Fire Department Incident Number: G1602544 Exposure Number: 0.0 Multi-Agency IC#: Incident Date: 03/05/16 Dispatch Time: 14:43:47 Arrival Time: 14:56:00 Controlled Time: Ending Time: 16:05:06 GT1 First-In Company: District G2725 Water problem, other None Incident Type: Mutual Aid: Method of Alarm: E911 Type of Weather: Air Temperature 69 Address, CSZ: SANTA ANA AUTO SUPPLY, 12600 W Census Tract: Fire Haz Sev Zone: Medium RESOURCES & CASUALTIES ______ Actions Taken 1: Provide manpower Actions Taken 2: Actions Taken 3: #Apparatus Resp Engine: 0 #Apparatus Resp Trk: 1 #Apparatus Resp Med: #Apparatus Resp Oth: Fire Svs Injury: 0 0 Fire Svs Fatal: 0 Non-FS Injury: Non-FS Fatal: PROPERTY & STUDIES ______ Property Losses: Content Losses: Property Value: Contents Value: Insurance Co: Building Ins:

Property Use: Motor vehicle or boat sales, services, r

Mixed Prop Use:

Detector

INCIDENT REPORT

| Hazmat Rel: Critical Inc: | None |
|--|---------------------------|
| Special Studies: | |
| | EMERGENCY MEDICAL SERVICE |
| and had been been been been been been been bee | |
| <pre>Number of Patients: Billing Care: Status: Transported to: # Patients Trans - Fire # Patients Trans - Amb:</pre> | |
| π ractenes rians - Anno. | |
| | COMMENTS |

**** GT1 ****

service call- weater removal capt velotta

GT1 assist with sprinkler repair and water removal