



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #381192

Service Request: 381192

Department: Public Works

Status: CLOSED

Priority: HIGH

Created at: September 22, 2014 08:04AM

Requester: Holmon

Home Phone:

Work Phone: 741-5956

Other Phone:

Created by: allens

Request: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Location: 7061 PATTERSON DR,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

File attachments: 1

Note #1 (09/22/14 by allens): Met with Mr. Allen Fowler, advised of City's policies & NPDES regulations, completed site walkaround inspection, minor rusty metal outside, advised to keep sheltered/covered up. Checked SWPPP, no violations, verbal

Task #1

Status: CLOSED on September 22, 2014 08:04AM by Allen Serna

Description: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Allen Serna

ECD:

Actions: A HIGH PRIORITY, 115.12 COMPLETED INSPECTION FORM, 115.10 EXPLAINED NPDES POLICIES, 115.2 INDUSTRIAL, 115.15 OTHER (SEE COMMENTS), 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.16 BMP FULLY IMPLEMENTED (INACTIVE)



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #397566

Service Request: 397566

Department: Public Works

Status: CLOSED

Priority: HIGH

Created at: September 22, 2015 08:39AM

Requester: Holmon

Home Phone:

Work Phone: 741-5956

Other Phone:

Created by: allens

Request: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP-VALENCE SURFACE TECHNOLOGIES

Location: 7061 PATTERSON DR,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

File attachments: 1

Note #1 (09/22/15 by allens): Met with Allen Fowler, advised of city's policies & NPDES regulations, completed site walkaround inspection, no violations.

Task #1

Status: CLOSED on September 22, 2015 08:39AM by Allen Serna

Description: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP-VALENCE SURFACE TECHNOLOGIES

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Allen Serna

ECD:

Actions: A HIGH PRIORITY, 115.12 COMPLETED INSPECTION FORM, 115.10 EXPLAINED NPDES POLICIES, 115.2 INDUSTRIAL, 115.15 OTHER (SEE COMMENTS), 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.16 BMP FULLY IMPLEMENTED (INACTIVE)



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #414173

Service Request: 414173

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: September 15, 2016 03:56PM

Requester: Soumelia Gountouma

Home Phone:

Work Phone: 5564

Other Phone:

Created by: liag

Request: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP-VALENCE SURFACE TECHNOLOGIES

Location: 7061 PATTERSON DR, SUITE

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

Task #1

Status: CLOSED on September 15, 2016 03:56PM by Soumelia Gountouma

Description: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP-VALENCE SURFACE TECHNOLOGIES

Comments: SPOKE WITH ALLEN FOWLER, OWNER. NO VIOLATIONS WERE OBSERVED. AN EDUCATIONAL BROCHURE WAS PROVIDED. CITY AND NPDES REGULATIONS WERE DISCUSSED.

Category: 115 NPDES INSPECTION

Division: ENVIRONMENTAL COMP

Completed by: Soumelia Gountouma

Assigned to: Albert Holmon III

Requester contacted:

ECD:

Actions: C LOW PRIORITY, 115.12 COMPLETED INSPECTION FORM, 115.10 EXPLAINED NPDES POLICIES, 115.3P1 OTHER SITES DETERMINED TO BE SIGNIFICANT CONTRIBUTORS, 115.2 INDUSTRIAL, 115.15 OTHER (SEE COMMENTS), 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.16 BMP FULLY IMPLEMENTED (INACTIVE)



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #305265

Service Request: 305265

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: December 03, 2010 11:40AM

Requester: HOLMON

Home Phone:

Work Phone:

Other Phone:

Created by: lorianah

Request: NPDES ANNUAL INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Location: 7061 PATTERSON DR,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

File attachments: 2

Note #1 (12/03/10 by lorianah): MET WITH ALLEN FOWLER. SOME STAINING OUTSIDE OF ACID SECONDARY CONTAINMENT AREA.

Note #2 (12/03/10 by lorianah): SAID HE WOULD REVISE METHOD FOR REMOVING ACID FROM CONTAINERS OUTSIDE AND REFLECT CHANGE IN OPERATION IN SWPPP.

Task #1

Status: CLOSED on December 03, 2010 11:40AM by Loriana Hornik

Description: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Loriana Hornik

ECD: December 3, 0010

Actions: A HIGH PRIORITY, 115.12 COMPLETED INSPECTION FORM, 115.10 EXPLAINED NPDES POLICIES, 115.2 INDUSTRIAL, 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.17 BMP PARTIALLY IMPLEMENTED (INACTIVE)



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #320011

Service Request: 320011

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: August 08, 2011 12:00AM

Requester: holmon

Home Phone:

Work Phone:

Other Phone:

Created by: lorianah

Request: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Location: 7061 PATTERSON DR, SUITE

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

Note #1 (08/08/11 by lorianah): no violations. both sample results from this year were very low in pH and high in SC. Allen Fowler was unaware of any spills that may have occurred. He thinks there may be some acid from the plating operation venting to the roof and plans on grabbing a sample of the roof water for analysis. He had employees powerwash the outside areas which may have contributed to the sample parameter exceedances.

Task #1

Status: CLOSED on August 08, 2011 12:00AM by Loriana Hornik

Description: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Loriana Hornik

ECD: August 8, 2011

Actions: A HIGH PRIORITY, 115.12 COMPLETED INSPECTION FORM, 115.10 EXPLAINED NPDES POLICIES, 115.2 INDUSTRIAL, 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.16 BMP FULLY IMPLEMENTED (INACTIVE)



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #340895

Service Request: 340895

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: August 07, 2012 12:00AM

Requester: HOLMON

Home Phone:

Work Phone:

Other Phone:

Created by: lorianah

Request: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Location: 7061 PATTERSON DR, SUITE

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

File attachments: 2

Note #1 (08/07/12 by lorianah): STAINING FROM A SPILL OF UNKNOWN LIQUID. EMPLOYEES CLEANED UP THE SPILL WHILE ON SITE.

Task #1

Status: CLOSED on August 07, 2012 12:00AM by Loriana Hornik

Description: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Loriana Hornik

ECD: August 7, 2012

Actions: A HIGH PRIORITY, 115.12 COMPLETED INSPECTION FORM, 115.10 EXPLAINED NPDES POLICIES, 115.2 INDUSTRIAL, 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.17 BMP PARTIALLY IMPLEMENTED (INACTIVE)



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #362875

Service Request: 362875
Department: Public Works
Status: CLOSED
Priority: HIGH
Created at: September 17, 2013 07:56AM

Requester: Holmon
Home Phone:
Work Phone: 741-5956
Other Phone:
Created by: allens

Request: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP, ANNUAL HIGH PRIORITY

Location: 7061 PATTERSON DR,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

File attachments: 1

Note #1 (09/17/13 by allens): Met with Allen Fowler, completed site inspection & checked paperwork, lab analysis results, advised to monitor rusty metals small amounts on ground, cleanup asap, 1 tote need to be positioned on secondary containment pallet, keep dumpster lids closed at all times

Task #1

Status: CLOSED on September 17, 2013 07:56AM by Allen Serna

Description: NPDES INDUSTRIAL INSPECTION OF COASTLINE METAL FINISHING CORP

Category: 115 NPDES INSPECTION

Assigned to: Albert Holmon III

Division: ENVIRONMENTAL COMP

Requester contacted:

Completed by: Allen Serna

ECD:

Actions: A HIGH PRIORITY, 115.12 COMPLETED INSPECTION FORM, 115.10 EXPLAINED NPDES POLICIES, 115.2 INDUSTRIAL, 115.15 OTHER (SEE COMMENTS), 115.11 PROVIDED EDUCATIONAL BROCHURES, 115.17 BMP PARTIALLY IMPLEMENTED (INACTIVE)