



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #426902

Service Request: 426902

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: June 13, 2017 04:15AM

Requester: Jose Vasquez

Home Phone:

Work Phone:

Other Phone:

Created by: josev

Request: REMOVE EXISTING CM / MMU & INSTALL TESTED MONITOR.

Location: BELGRAVE AVE / VALLEY VIEW ST,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

Total cost: \$14.31

Task #1

Status: CLOSED on June 13, 2017 04:20AM by Jose Vasquez

Description: No task description

Comments: REMOVED CONFLICT MONITOR / MMU & INSTALLED TESTED MONITOR #141201068.

Category: 700 SIGNAL MAINTENANCE

Division: ENGR SERVICES

Completed by: Jose Vasquez

Total task cost: \$14.31

Actions: 700.26 OTHER (SEE COMMENTS)

Assigned to: Jose Vasquez

Requester contacted:

ECD:

Labor Costs

Name	Reg	OT	Total
Jose Vasquez	0.2 hours	0 hours	\$14.31
TOTAL	0.2 hours	0 hours	\$14.31



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #427216

Service Request: 427216
Department: Public Works
Status: CLOSED
Priority: EMERGENCY
Created at: June 16, 2017 01:00PM

Requester: Dai Vu
Home Phone:
Work Phone:
Other Phone:
Created by: josev

Request: Check intersection operation. Resident says she drove by and observed the intersection going in and out of red and green indications.

Location: BELGRAVE AVE / VALLEY VIEW ST,

Public Property: NO
Square Feet:

Eng. Permit:
Police Num.:
Fire Num.:

Total cost: \$104.02

Task #1

Status: CLOSED on June 16, 2017 03:00PM by Jose Vasquez

Description: No task description

Comments: I arrived and observed the intersection for several cycles. Everything was working properly. I opened the controller cabinet, check the logs, equipment and voltages. Everything was working properly. I tested the fire departments EVP system for possible malfunctions and found that to be working properly. I watched the intersections for several more cycles and found everything to be working as designed.

Category: 700 SIGNAL MAINTENANCE

Assigned to: Jose Vasquez

Division: ENGR SERVICES

Requester contacted:

Completed by: Jose Vasquez

ECD:

Total task cost: \$104.02

Actions: 700.26 OTHER (SEE COMMENTS)

Labor Costs

Name	Reg	OT	Total
Jose Vasquez	1.0 hours	0.5 hours	\$104.02
TOTAL	1.0 hours	0.5 hours	\$104.02



GARDEN GROVE PUBLIC WORKS DEPARTMENT SERVICE REQUEST #428868

Service Request: 428868

Department: Public Works

Status: CLOSED

Priority: NORMAL

Created at: July 11, 2017 02:45PM

Requester: Jose Vasquez

Home Phone:

Work Phone:

Other Phone:

Created by: josev

Request: PREVENTIVE MAINTENANCE. Assigned to Yanie (Siemens Tech).

Location: BELGRAVE AVE / VALLEY VIEW ST,

Public Property: NO

Square Feet:

Eng. Permit:

Police Num.:

Fire Num.:

Total cost: \$58.46

Task #1

Status: CLOSED on July 11, 2017 03:30PM by Jose Vasquez

Description: No task description

Comments: VACUUMED CONTROLLER CABINET-REPLACED AIR FILTER-PERFORMED P.M. SCHEDULE-WALKED INTERSECTION-REMOVED GRAFFITI FROM CONTROLLER CABINET AND POLES.

Category: 700 SIGNAL MAINTENANCE

Assigned to: Jose Vasquez

Division: ENGR SERVICES

Requester contacted:

Completed by: Jose Vasquez

ECD:

Total task cost: \$58.464

Actions: 700.26 OTHER (SEE COMMENTS), 740.1 GRAFFITI REMOVED/COVERED

Labor Costs

Name	Reg	OT	Total
Jose Vasquez	0.8 hours	0 hours	\$58.46
TOTAL	0.8 hours	0 hours	\$58.46