



City of Garden Grove Public Works Department:

Project Name:  
**Chapman Ave (Brookhurst at Nelson)**  
**Residential Streets – Sapphire, Santa Rita,**  
**Wild Goose, Healey**  
 Project No.: 7280

Page No. 1 of 2

REPORT NO. 47

Date: 9/20/18

Day: Thursday

Shift Start:

7:00 AM

Stop:

3:30 PM

**DAILY CITY INSPECTION**

**CHAPMAN AVE.**

**REPORT**

Weather												
Sunny			AM									
Sunny			PM									
Temperature												
71			Min									
80			Max									

  

			(1)	(2) Traffic Control						
			(2)	(6) Full Depth Reclamation						
			(3)							
			(4)							
			(5)	IDLE */off site						
<b>EQUIP. NO.</b>	<b>NO. MEN</b>	<b>DESCRIPTION (EQUIPMENT/LABOR)</b>						<b>Contractor</b>	<b>REMARKS (Reason for idleness or other remarks)</b>	
	1	Tom Lorenz Foreman	2	6				RJ Noble		
	1	F250	2	6				RJ Noble		
406, 450	2	Skip Loader		8				RJ Noble		
	1	Gary Quimlian Water Truck		8				RJ Noble	Rental	
	1	Adam Penix Operator		8				Precision		
	1	Smooth Drum Roller		8				Precision		
3-017	1	F350		8				RJ Noble		
349	1	Roller		8				RJ Noble		
520	2	Motor Grader		8				RJ Noble		
	1	Armando Prieto Foreman		8				VE Tree Trimming		
	1	Rafael Arajo Laborer		8				VE Tree Trimming		
	1	Alberto Garcia Laborer		8				VE Tree Trimming		
	1	Adolfo Rozes Laborer		8				VE Tree Trimming		
Alice	1	F550		8				VE Tree Trimming		
Becky	1	F650 w/Chipper		8				VE Tree Trimming		

### Progress:

Permanent traffic control closure is in place. Traffic is in the middle lanes and construction is in the outside lanes. ASE onsite to observe micro cracking operations in the #2 lane in the westbound direction from SP 10+88 to SP 49+58. Met City of Garden Grove, Tom Hall, RJN and ASE onsite to review concrete work and paving operations for Saturday 9/22/18. Spectrum Cable onsite to continue repairing damaged cable from SP 10+88 to SP 17+00 in westbound direction. VE onsite to remove tree at 10281 Chapman. Tree was removed and stump was ground down. RJN has a water truck onsite to keep cement treated base moistened.

Inspector Hours=

Reg

OT

DT

Inspector



8

.5

PAT SHEN

### PHOTOS: 9/19/18



Removing tree on Chapman.



Micro cracking