

Garden Grove Fire Department Station: G01

Location: 10181 LARSON AVE GARDEN GROVE CA 92843

Lat/Long:

N 33° 46′ 20.43″ W 117° 57′ 5.73″

Location Type: 1 - Street address

Map Page: 798E7

Incident Type: 111 - Building fire

FDID: 30035

Incident #: **2019--045836** Exposure ID: **39603929**

Exposure #: 0

Incident Date: **04/24/2019**Dispatch Run #: **F191140178**

Report Completed by:	Kuhlman , Scott A	ID: 4744	Date: 05/12/2019	
Report Reviewed by:	Garcia , Drew R	ID: 3592	Date: 05/14/2019	
Report Printed by:	Guardi, Lisa	ID: 4433	Date: 6/6/2019 Time: 11:21	

Structure Type: Enclosed building Property Use: 419 - 1 or 2 family dwelling						
Automatic Extinguishment System Present: Detectors Present: Cause of Ignition: Cause undetermined after investigation					ter	
Aid Given or Received: Mutual aid received Primary action taken: 10 - Fire control or extinguishment, other			other			
Losses	Pre-Incident Values					
Property:	Property:	Civilian Injuri	ies:	0	Fire Service Injuries:	0
Contents:	Contents:	Civilian Fatali	ities:	0	Fire Service Fatalities:	0
Total:	Total:	Total Casualt	ies:	0	Total Fire Service Casualties:	0
Total # of apparatus on call:		6	Total # of	f personr	nel on call:	15

NARRATIVE (2)

Narrative Title: Structure Fire
Narrative Author: Garcia, Drew
Narrative Date: 04/24/2019 18:33:37

Narrative Apparatus ID: GE1

Narrative:

GE1 responded to a correct address of 10181 Larson to find a detached garage fully involved to the rear of the main house. GE1 went into the attack mode and pulled a 1 3/4' preconnect along the delta side of the house and attacked the fire. GE1 was assigned Fire Attack and noticed power lines down to the rear alley, along with small explosions heard in the detached garage. GE1 pulled back and hit the fire from a safe area and requested Edison. GE3 assumed DIV C and denied access to the rear alley. The fire was extinguished and fire damage was limited to the backyard. The back yard contained the detached garage, and several sheds. One shed was fully destroyed, along with copious amounts belongings in the rear yard. GI3 was on scene and conducting the investigation. See GI3's report for full investigation information.

The building department arrived on scene and red tagged the building. GE1 met with the owner and had her sign a property release stating to post a 24 hour fire watch, and not occupy the building due to the red tagging. The owner was advised to coordinate with the building department as to when they could reoccupy the structure. GE1 complete.

Fire Controlled Date	/ Time:	4/24/2019 1:08:00 PM	
Unit	GB1	Unit	GE1
Туре:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	0
# of People	i i i i i i i i i i i i i i i i i i i	# of People	3
Alarm	04 /24/2019 12:42:58	Alarm	04 /24/2019 12:42:58
Dispatched	04 /24/2019 12:43:46	Dispatched	04 /24/2019 12:43:46
Enroute	04 /24/2019 12:44:42	Enroute	04 /24/2019 12:44:34
Arrived	04 /24/2019 12:51:48	Arrived	04 /24/2019 12:55:12
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	04 /24/2019 14:56:29	Cleared Scene	04 /24/2019 15:12:34
In Quarters	//::	In Quarters	/ / : :
In Service	04 /24/2019 14:56:29	In Service	04 /24/2019 15:12:34
Unit	GE3	Unit	GE5
Туре:	Engine	Туре:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	0
# of People	3	# of People	4
Alarm	04 /24/2019 12:42:58	Alarm	04 /24/2019 12:42:58
Dispatched	04 /24/2019 12:43:46	Dispatched	04 /24/2019 12:57:53
Enroute	04 /24/2019 12:44:59	Enroute	04 /24/2019 12:58:18
Arrived	04 /24/2019 12:52:59	Arrived	04 /24/2019 13:05:08
Cancelled	/ / : :	Cancelled	//::
Cleared Scene	04 /24/2019 14:58:45	Cleared Scene	04 /24/2019 14:07:47
In Quarters	04 /24/2019 15:09:56	In Quarters	04 /24/2019 14:08:05
In Service	04 /24/2019 14:58:45	In Service	04 /24/2019 14:07:47
Unit	GE6	Unit	GI3
Туре:	Engine	Туре:	Other apparatus/resource
Use:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	0
# of People	3	# of People	1
Alarm	04 /24/2019 12:42:58	Alarm	04 /24/2019 12:42:58
Dispatched	04 /24/2019 12:50:57	Dispatched	04 /24/2019 12:43:46
Enroute	04 /24/2019 12:50:57	Enroute	04 /24/2019 12:44:59
Arrived	04 /24/2019 12:53:10	Arrived	04 /24/2019 12:52:59
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	04 /24/2019 14:02:10	Cleared Scene	04 /24/2019 14:58:45
In Quarters	04 /24/2019 15:14:27	In Quarters	/ / : :
In Service	04 /24/2019 14:02:10	In Service	/ / : :

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Storage area, other	Heat Source	Undetermined
Item First Ignited	Undetermined	Fire Is Confined To Object Of Origin	
Type Of Material	Undetermined	Cause Of Ignition	Cause undetermined after investigation
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	Unattended or unsup	ervised person,	

Structure Type	Enclosed building	Building Status	In normal use
# Of Stories At Above Grade	1	# Of Stories Below Grade	0
Square Feet		Length	12
Width	20	Floor Of Origin	1
Fire Spread	Beyond building of or	igin	
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0

ARSON			
Agency Name	Agency Address	Agency Phone	

PEOPLE PERSON 1		· · · · · · · · · · · · · · · · · · ·	
Telephone Number	7145395565	Involvement	Caller
Name	TIRE, METRO INC	Date of Birth	
Address	10502 GARDEN GROVE BLVD GARDEN GROVE, CA 92843-		

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service
Was this patient homeless?	Not applicable
Fire Incident - What happened?	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Acosta, Alberto			GE6
Crawford, Timothy A			GE1
Furuta, Garret M			GE5
Gabbard, James			GB1
Garcia, Drew R			GE1
Howey, Shane S			GE3
Jacobs, Michael			GE5
Kuhlman, Scott A			GE3
Lovely, Norman M			GE6
Marquez Jr., John M			GE3
Nguyen, Thanh			GE5
Norrdin, Eric S			GE1
Ronstadt, Richard			GE5
Van Wie, Ryan			GE6

Member Making Report (Captain Scott A Kuhlman):	
Incident Reviewer (Captain Drew R Garcia):	