



Location: 7291 GARDEN GROVE BLVD GARDEN GROVE CA 92841 EAGLE DR	Incident Type: 162 - Outside equipment fire
Lat/Long: N 33° 46' 26.01" W 118° 0' 15.39"	FDID: 30035 Incident #: 2019-908860 Exposure ID: 41727079 Exposure #: 0 Incident Date: 07/28/2019 Dispatch Run #: F192090361
Location Type: 1 - Street address Map Page: 797H6 Cross Street, Directions or National Grid: EAGLE DR	

Report Completed by:	Nguyen , Thanh	ID: 0167	Date: 07/29/2019
Report Reviewed by:	Nguyen , Thanh	ID: 0167	Date: 07/29/2019
Report Printed by:	Guardi, Lisa	ID: 4433	Date: 8/1/2019 Time: 10:56

Structure Type:	Property Use: 965 - Vehicle parking area		
Automatic Extinguishment System Present: <input type="checkbox"/>	Detectors Present: <input type="checkbox"/>	Cause of Ignition: Failure of equipment or heat source	
Aid Given or Received: None	Primary action taken: 10 - Fire control or extinguishment, other		
Losses	Pre-Incident Values		
Property:	Property:	Civilian Injuries: 0	Fire Service Injuries: 0
Contents:	Contents:	Civilian Fatalities: 0	Fire Service Fatalities: 0
Total:	Total:	Total Casualties: 0	Total Fire Service Casualties: 0
Total # of apparatus on call: 5		Total # of personnel on call: 13	

NARRATIVE (2)
Narrative Title: n/a Narrative Author: Waldschmidt, David Narrative Date: 07/29/2019 08:18:50 Narrative Apparatus ID: n/a Narrative: cancelled by ge5

NARRATIVE (3)
Narrative Title: n/a Narrative Author: Nguyen, Thanh Narrative Date: 07/29/2019 19:38:13 Narrative Apparatus ID: n/a Narrative: GE5 arrived on scene to find a street light in a driveway of a business that was on fire. GE5 extinguished the fire with a dry chemical extinguisher. GE5 had Metro Net contact GGPD to contact the property owner.

APPARATUS			
Unit	GB1	Unit	GE4
Type:	Chief officer car	Type:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	()	Response Mode:	()
# of People	1	# of People	3
Alarm	07 /28/2019 20:40:52	Alarm	07 /28/2019 20:40:52
Dispatched	07 /28/2019 20:44:10	Dispatched	07 /28/2019 20:44:10
Enroute	07 /28/2019 20:45:44	Enroute	07 /28/2019 20:45:47
Arrived	-- /-- /-- -- :-- :--	Arrived	07 /28/2019 20:48:28
Cancelled	07 /28/2019 20:48:42	Cancelled	07 /28/2019 20:48:29
Cleared Scene	07 /28/2019 20:48:42	Cleared Scene	07 /28/2019 20:48:30
In Quarters	07 /28/2019 20:48:49	In Quarters	07 /28/2019 20:50:15
In Service	07 /28/2019 20:48:42	In Service	07 /28/2019 20:48:30
Unit	GE5	Unit	GM1
Type:	Engine	Type:	ALS unit
Use:	Suppression	Use:	EMS
Response Mode:	()	Response Mode:	()
# of People	4	# of People	2
Alarm	07 /28/2019 20:40:52	Alarm	07 /28/2019 20:40:52
Dispatched	07 /28/2019 20:44:10	Dispatched	07 /28/2019 20:44:21
Enroute	07 /28/2019 20:44:31	Enroute	07 /28/2019 20:45:25
Arrived	07 /28/2019 20:47:55	Arrived	-- /-- /-- -- :-- :--
Cancelled	-- /-- /-- -- :-- :--	Cancelled	07 /28/2019 20:47:53
Cleared Scene	07 /28/2019 20:57:07	Cleared Scene	07 /28/2019 20:47:53
In Quarters	-- /-- /-- -- :-- :--	In Quarters	07 /28/2019 20:49:20
In Service	07 /28/2019 20:57:07	In Service	07 /28/2019 20:47:53
Unit	GT1		
Type:	Truck or aerial		
Use:	Suppression		
Response Mode:	()		
# of People	3		
Alarm	07 /28/2019 20:40:52		
Dispatched	07 /28/2019 20:44:21		
Enroute	07 /28/2019 20:45:13		
Arrived	-- /-- /-- -- :-- :--		
Cancelled	07 /28/2019 20:48:07		
Cleared Scene	07 /28/2019 20:48:07		
In Quarters	07 /28/2019 21:14:49		
In Service	07 /28/2019 20:48:07		
Number Of People not on apparatus: 0			

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Highway, parking lot, street: on or near	Heat Source	Heat from powered equipment, other
Item First Ignited	Electrical wire, cable insulation	Fire Is Confined To Object Of Origin	
Type Of Material		Cause Of Ignition	Failure of equipment or heat source
Factor Contributing To Ignition	Electrical failure, malfunction, other		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	Equipment Involved	Lamp, lighting, other
Equipment Power Source	Electrical, other	Equipment Portability	Stationary

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service
Was this patient homeless?	Not applicable
Fire Incident - What happened?	

PERSONNEL ON CALL			
Name	Personnel Rank	Role(s)	Apparatus
Camberos, Jose J			GE5
Mickelsen, Mark	Firefighter		GT1
Nguyen, Son	Engineer		GE4
Nguyen, Thanh			GE5
Ronstadt, Richard			GE5
Scherer, Scott A	Engineer		GT1
Stroh, Bill	Captain		GT1
Thorson, Eric	Paramedic / Tiller		GE4
Truhill, Justin P	Battalion Chief		GB1
Waldschmidt, David S	Captain		GE4
White, Jonathan	Firefighter / Paramedic		GM1
Williams, Gregory D	Firefighter / Paramedic		GM1
Yorke, Jeremie E			GE5

Member Making Report (Captain Thanh Nguyen): _____

Incident Reviewer (Captain Thanh Nguyen): _____