

### Garden Grove Fire Department

Station: **G07** Shifts Or Platoon: **A** 

# Location: 14144 BROOKHURST ST

GARDEN GROVE CA 92843

Lat/Long:

N 33° 45′ 26.62″ W 117° 57′ 16.9″

Location Type: 1 - Street address

Map Page: 828E2

# Incident Type: 111 - Building fire

FDID: 30035

Incident #: **2019-907886** Exposure ID: **41256412** 

Exposure #: 0

Incident Date: **07/07/2019**Dispatch Run #: **F191880219** 

Report Completed by:	Pardoen , Brent C	<b>ID:</b> 3376	<b>Date:</b> 07/07/2019	
Report Reviewed by:	Nguyen , Thanh	<b>ID:</b> 0167	Date: 07/23/2019	
Report Printed by:	Pollock, Amanda	ID:	Date: 8/28/2019 Time: 11:51	

Structure Typ	pe: Enclosed building Property	Use: <b>50</b> 0	0 - M	lercantile,	busin	ess, other	
Automatic Ex	tinguishment System Present:	Detectors	s Pre	sent: 🗹 C	ause o	f Ignition: Unintentional	
Aid Given or	Received: Automatic aid receiv	red Prin	nary	action take	n: <b>10</b>	- Fire control or extinguishme	nt, other
Losses	Pre-Incident Values						
Property:	Property:	Civilian	Inju	ries:	0	Fire Service Injuries:	0
Contents:	Contents:	Civilian	Fata	ilities:	0	Fire Service Fatalities:	0
Total:	Total:	Total C	asua	lties:	0	Total Fire Service Casualties:	0
Total # of ap	paratus on call:		7	Total # of	persor	nnel on call:	18

#### **Neighboring Agencies**

Agency Name: Orange County Fire Authority

Agency ID: 30065 Agency Type: Fire

### **NARRATIVE (2)**

Narrative Title: STRUCTURE FIRE COMMERCIAL

Narrative Author: Rieth, Mike

Narrative Date: 07/07/2019 20:38:33

Narrative Apparatus ID: GE7

#### Narrative:

GE7 RESPONDED TO A COMMERCIAL STRUCTURE FIRE LOCATED AT 14140 BROOKHURST STREET IN THE CITY OF GARDEN GROVE. ON ARRIVAL GE7 NOTICED FIRE VISIBLE FROM THE ROOF OF THE 2 STORY COMMERCIAL BUILDING. ON THE ROOF IT WAS FOUND THAT A HEAT VENT WAS ON FIRE AND THE SURROUNDING ROOF AND PARAPET WAS ALSO ON INVOLVED. GE7 MADE AN ATTACK ON THE FIRE USING A HANDLINE PUTTING OUT THE FIRE ON THE ROOF. GROVE LIGHT FORCE 1 PROVIDED VERTICAL VENTILATION AND ACCESS TO THE PARAPET TO FURTHER ASSIST IN EXTINGUISHING THE FIRE. ADDITIONAL FIRE UNITS DISCOVERED SMOKE IN BOTH UNITS DIRECTLY BELOW THIS HEAT VENT AND FIRE IN THE WALL TO THE REAR OF EACH UNIT. THE FIRE WAS COMPLETELY EXTINGUISHED IN ROUGHLY 35 MINUTES. UPON INVESTIGATION OF THE AREAS INVOLVED IT WAS DETERMINED THAT THE FIRE ORIGINATED IN THE COOKING AREA LOCATED AT THE RESTAURANT ON THE BOTTOM FLOOR ADDRESSED AS 14140 BROOKHURST. FIRE DAMAGE WAS PRESENT GOING FROM THE HEATING VENT AREA AND EXTENDING ALL THE WAY TO THE ROOF LINE. PUBLIC HEALTH ARRIVED SHORTLY AND INSPECTED THE SUSPECTED AREA OF ORIGIN. THE BUILDING DEPARTMENT WAS ALSO REQUESTED AND STATED THAT THEY WOULD ARRIVE ON THE MORNING OF MONDAY JULY 8TH. THE UTILITIES WERE CUT TO THE STRUCTURE AND WAS RED TAGGED UNITL CLEARED BY THE BUILDING DEPARTMENT. THE OCCUPANTS OF THE THREE UNITS THAT WERE INVOLVED WERE CONTACTED AND SIGNED PROPERTY RELEASE FORMS. NO INJURIES OCCURED ON THE FIRE AND ALL OCCUPANTS WERE EVACUATED SAFETLY.

CAPTAIN RIETH

Jnit	GB1	Unit	GE1
Гуре:	Chief officer car	Type:	Engine
Jse:	Suppression	Use:	Suppression
Response Mode:	0	Response Mode:	()
# of People	1	# of People	3
Alarm	07 /07/2019 13:54:12	Alarm	07 /07/2019 13:54:12
Dispatched	07 /07/2019 13:56:03	Dispatched	07 /07/2019 13:56:03
Enroute	07 /07/2019 13:56:55	Enroute	07 /07/2019 13:56:57
Arrived	07 /07/2019 14:05:13	Arrived	07 /07/2019 14:05:21
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	07 /07/2019 16:06:18	Cleared Scene	07 /07/2019 16:44:31
In Quarters	07 /07/2019 16:59:03	In Quarters	07 /07/2019 16:55:10
In Service	07 /07/2019 16:06:18	In Service	07 /07/2019 16:44:31
Unit	GE3	Unit	GE7
Гуре:	Engine	Туре:	Engine
Use:	Suppression	Use:	Suppression
Response Mode:	()	Response Mode:	()
# of People	3	# of People	3
Alarm	07 /07/2019 13:54:12	Alarm	07 /07/2019 13:54:12
Dispatched	07 /07/2019 14:16:43	Dispatched	07 /07/2019 13:56:03
Enroute	07 /07/2019 14:16:43	Enroute	07 /07/2019 13:56:56
Arrived	07 /07/2019 14:16:43	Arrived	07 /07/2019 13:58:35
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	07 /07/2019 16:07:18	Cleared Scene	07 /07/2019 16:59:47
In Quarters	07 /07/2019 16:14:09	In Quarters	07 /07/2019 17:32:54
In Service	07 /07/2019 16:07:18	In Service	07 /07/2019 16:59:47
Jnit	GLA6	Unit	GM1
Гуре:	Light and air unit	Type:	ALS unit
jse:	Suppression	Use:	EMS
Response Mode:	()	Response Mode:	()
# of People	3	# of People	2
Alarm	07 /07/2019 13:54:12	Alarm	07 /07/2019 13:54:12
Dispatched	07 /07/2019 14:10:22	Dispatched	07 /07/2019 13:56:03
Inroute	07 /07/2019 14:11:57	Enroute	07 /07/2019 13:56:49
Arrived	07 /07/2019 14:39:44	Arrived	07 /07/2019 14:03:19
Cancelled	/ / : :	Cancelled	/ / : :
Cleared Scene	07 /07/2019 16:42:19	Cleared Scene	07 /07/2019 16:44:57
in Quarters	07 /07/2019 16:42:25	In Quarters	07 /07/2019 17:17:50
in Service	07 /07/2019 16:42:19	In Service	07 /07/2019 16:44:57
Jnit	GT1	*** ********	07  07 2013 10.77.37
Гуре:	Truck or aerial		
Jse:	Suppression		
Response Mode:	()		
of People	3		
Alarm	07 /07/2019 13:54:12		
Dispatched	07 /07/2019 13:56:03		
inroute	07 /07/2019 13:57:02		
Arrived	07 /07/2019 13:37:02		
Cancelled	/ / : :		
Cleared Scene	07 /07/2019 16:44:57		
in Quarters	07 /07/2019 16:51:36		
	97 1977 6913 19.11.39		

FIRE			
Acres Burned	None or Less Than One	Acres Burn From Wildland Form	False
Area Of Fire Origin	Cooking area, kitchen	Heat Source	Spark, ember, or flame from operating equipment
Item First Ignited	Cooking materials, including edible materials	Fire Is Confined To Object Of Origin	
Type Of Material		Cause Of Ignition	Unintentional
Factor Contributing To Ignition	Undetermined		
Human Factors Contributing	None		
Equipment Involved In Ignition Flag	True	<b>Equipment Involved</b>	Stove, heating
Equipment Power Source	Natural gas or other lighter- than-air gas	<b>Equipment Portability</b>	Stationary

STRUCTURE FIRE			
Structure Type	Enclosed building	Building Status	In norma
# Of Stories At Above Grade	2	# Of Stories Below Grade	0
Square Feet	5000	Length	
Width		Floor Of Origin	2
Fire Spread	Confined to building of origin	_	
Minor Damage	0	Significant Damage	0
Heavy Damage	0	Extreme Damage	0
Presence Of Detectors	Present	Type Of Detection System	Smoke
Detector Power Supply	Undetermined	<b>Detector Operation</b>	Detector operated
<b>Detector Effectiveness</b>	Detector alerted occupants, occupants responded	<b>Detector Failure Reason</b>	,
Presence OF AES	Present	Type Of AES	

PEOPLE PERSON 1			
Telephone Number	9095618924	Involvement	Caller
Name	GGPD/CELL	Date of Birth	
Address	14271 CORPORATE DR G	SARDEN GROVE, CA 92843-	

CUSTOM FIELDS FORM	
What happened?	We provided fire and rescue service
Was this patient homeless?	Not applicable
Fire Incident - What happened?	We investigated - company officer determined cause
Fire started due to fireworks?	No
Injury related to fireworks?	No

Member Making Report (Captain Brent C Pardoen):	 	
Incident Reviewer (Captain Thanh Nguyen):		