

**permit#** 22-5858**location:** 5302 STANFORD AVE**permit status:** **Final****created on:** Dec 15, 2022**issued on:** Dec 15, 2022**expiration:** Sep 09, 2023**contractor:** AIR CONCEPTS**work type:** Residential Mechanical Permit**waste management plan:** not applicable or not yet created**work description** CODE CASE# 189835. INSTALL (N) 3 TON HEAT PUMP CONDENSER IN RIGHT SIDE YARD, C/O FAU INSIDE ATTIC, INSTALL DISCONNECT SWITCH, C/O DUCTING THROUGHOUT**inspection status** Final

## inspections:

date	status	requested inspection	assigned to	inspector phone
Feb 14, 2023	<u>Approved (Inspection passed)</u>	935 Mechanical Final	Diane Belair	tel: (tel:)
Feb 14, 2023	<u>Approved (Inspection passed)</u>	310 Air Conditioning / Heating	Diane Belair	tel: (tel:)
Jan 31, 2023	<u>Approved (Inspection passed)</u>	930 Electrical Final	Diane Belair	tel: (tel:)
Jan 31, 2023	<u>Corrections (Outstanding issues, refer to correction notice)</u>	310 Air Conditioning / Heating	Diane Belair	tel: (tel:)

### Legend

**Approved**

Inspection passed

**Partial Pass**

A portion was approved, okay to proceed

**Pending**

Inspection status not recorded

**Not Ready**

Insufficient progress to perform inspection

**Corrections**

Outstanding issues, refer to correction notice

**No Access**

Job site not available for entry

**Cancel**

Inspection request called off

**permit#** 16-3002**location:** 5302 STANFORD AVE**permit status:** **Final****created on:** Oct 12, 2016**issued on:** Oct 12, 2016**expiration:** Apr 17, 2017**contractor:** PREFERRED RECONSTRUCTION**work type:** Residential Plumbing Permit**waste management plan:** not applicable or not yet created**work description** REPLACE 8FT COPPER WATER LINE IN GARAGEView PDF file (<https://ch.ci.garden-grove.ca.us/archives/public/download/236224>)**inspection status** Final

## inspections:

date	status	requested inspection	assigned to	inspector phone
Oct 19, 2016	Approved (Inspection passed)	925 Plumbing Final	Forest Johnson CSG	714-741-5164 (tel:714-741-5164)

### Legend

**Approved**

Inspection passed

**Partial Pass**

A portion was approved, okay to proceed

**Pending**

Inspection status not recorded

**Not Ready**

Insufficient progress to perform inspection

**Corrections**

Outstanding issues, refer to correction notice

**No Access**

Job site not available for entry

**Cancel**

Inspection request called off

**permit#** 16-2918**location:** 5302 STANFORD AVE**permit status:** **Final****created on:** Oct 04, 2016**issued on:** Oct 04, 2016**expiration:** Apr 17, 2017**contractor:** PREFERRED RECONSTRUCTION**work type:** Residential Repair**waste management plan:** not applicable or not yet created**work description** REPAIR TO GARAGE DUE TO CAR ACCIDENT (LIKE FOR LIKE)View PDF file (<https://ch.ci.garden-grove.ca.us/archives/public/download/236225>)**inspection status** Final

## inspections:

date	status	requested inspection	assigned to	inspector phone
Oct 19, 2016	Approved (Inspection passed)	940 Building Final	Forest Johnson CSG	714-741-5164 (tel:714-741-5164)
Oct 17, 2016	Approved (Inspection passed)	160 Brown Coat	Forest Johnson CSG	714-741-5164 (tel:714-741-5164)
Oct 12, 2016	Approved (Inspection passed)	135 Framing	Greg Griffith CSG	tel: (tel:)
Oct 12, 2016	Approved (Inspection passed)	150 Exterior Lath	Greg Griffith CSG	tel: (tel:)
Oct 10, 2016	Partial Pass (A portion was approved, okay to proceed)	135 Framing	Greg Griffith CSG	tel: (tel:)

### Legend

**Approved**

Inspection passed

**Partial Pass**

A portion was approved, okay to proceed

**Pending**

Inspection status not recorded

**Not Ready**

Insufficient progress to perform inspection

**Corrections**

Outstanding issues, refer to correction notice

**No Access**

Job site not available for entry

**Cancel**

Inspection request called off

**permit#** 95554

**location:** 5302 STANFORD AVE

**permit status:** **Final**

**created on:**

**issued on:** Aug 25, 2008

**expiration:**

**contractor:** B.M.L. CONSTRUCTION, INC.

**work type:** Residential Reroof

**waste management plan:** not applicable or not yet created

**work description** TYPE: REPAIRS. reroof-comp shingles over exist. comp sh ingles.

View PDF file (<https://ch.ci.garden-grove.ca.us/archives/public/download/109172>)

**inspection status** Final No inspections in System

**permit#** 547

**location:** 5302 STANFORD AVE

**permit status:** Finaled

**created on:**

**issued on:** Feb 07, 1990

**expiration:**

**contractor:** ROY L. CHAFEY ROOFING

**work type:** Residential Reroof

**waste management plan:** not applicable or not yet created

**work description** TYPE: REPAIRS. T/O ROCK 2 LAYERS #15 FELT COMP SHINGLES

**inspection status** Finaled No inspections in System

**permit#** 126659A

**location:** 5302 STANFORD AVE

**permit status:** Finaled

**created on:**

**issued on:** Aug 01, 1982

**expiration:**

**contractor:** NONE LISTED

**work type:** Residential

**waste management plan:** not applicable or not yet created

**work description TYPE:** PLUMBING. PLUMBING

**inspection status** Finaled No inspections in System



**permit#** 113239A

**location:** 5302 STANFORD AVE

**permit status:** Finaled

**created on:**

**issued on:** Jan 01, 1980

**expiration:**

**contractor:** NONE LISTED

**work type:** Residential

**waste management plan:** not applicable or not yet created

**work description TYPE:** PLUMBING. PLUMBING

**inspection status** Finaled No inspections in System